

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R142a.

5. LEASE DESIGNATION AND SERIAL NO.

IC 032233 - (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|---|---|
| 1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR Humble Oil & Refining Company | 8. FARM OR LEASE NAME Bowers "A" Federal |
| 3. ADDRESS OF OPERATOR P.O. Box 1600, Midland, Texas 79701 | 9. WELL NO. 32 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 S/L, 1980 E/L, Sec. 30, T18S, R38E | 10. FIELD AND POOL, OR WILDCAT Hobbs Blinebry-Drinkard |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3646 GR. |
| | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S30, T18S, R38E |
| | 12. COUNTY OR PARISH Lea |
| | 13. STATE New Mexico |

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROCEDURE:

Notify USGS, OCC and offset operators of intent to plug and abandon.

1. Circulate both casing strings with gelled mud (25 sacks of gel in 100 barrels produced water).
2. Spot 100' cement plugs in 3 1/2" casings at 6650' (Drinkard).
3. Spot 100' cement plugs in 3 1/2" casings at 5800' (Blinebry).
4. Spot 100' cement plugs in 3 1/2" casings at 4050' (San Andres).
5. Cut off both 3 1/2" casing strings, pull and spot 100' cement plug above cuts.
6. Cut off 9 5/8" casing and pull. Spot 100' cement plug in casing or at top of anhydrite at 1400', whichever is higher.
7. Spot 100' cement plug at 13 3/8" casing shoe.
8. Spot 20' cement plug at surface.
9. Rig wellhead for abandonment and install marker.

NOTE: Blinebry is west casing
Drinkard is east casing
Follow each cement plug with gelled mud.

18. I hereby certify that the foregoing is true and correct

SIGNED

B.M. Bradley

(This space for Federal or State office use)

TITLE District Superintendent

DATE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

PLUG AND ABANDON, ANDREWS DISTRICT

Date April 26, 1972
Field Supt. J. C. Sherrill

Well Bowers "A" Federal No. 32
Field Hobbs Pool

Objective: Plug and Abandon.

Drilled Depth 7075' Plug Back Depth 7075' Prod. Csg: Size 3 1/2"
Min. & Max. pff 7.7 Min. Grade J-55 Set at 7053'
7.7 6140'

Top Cement 2900' T.S. Production Interval Blinebry & Drinkard
5940'-5954' 5825'-5876'
Perf. Csg: Interval (s) 6974'-6982' 5887'-5901'

Tubing Size _____ Grade _____ No. Joints _____ Set at _____

Bottom Arrangement CI BP @ 5794' w/cmt. (Blinebry)
CI BP @ 6300' w/8'.cmt. plug on top. (Drinkard)

^{GR}
~~RM~~ Elev. 3646' Zero Point 11.8 Feet Above GR Casinghead Flange

Latest Well Test: _____

Note: East casing string is Drinkard.

West casing string is Blinebry.

PROCEDURE:

Attached.


PLUG AND ABANDON PROCEDURE

Notify USGS, OCC and offset operators of intent to plug and abandon.

1. Circulate both casing strings with gelled mud (25 sacks of gel in 100 barrels produced water).
2. Spot 100' cement plugs in 3 1/2" casings at 6650' (Drinkard).
3. Spot 100' cement plugs in 3 1/2" casings at 5800' (Blinebry).
4. Spot 100' cement plugs in 3 1/2" casings at 4050' (San Andres).
5. Cut off both 3 1/2" casing strings, pull and spot 100' cement plug above cuts.
6. Cut off 9 5/8" casing and pull. Spot 100' cement plug in casing or at top of anhydrite at 1400', whichever is higher.
7. Spot 100' cement plug at 13 3/8" casing shoe.
8. Spot 20' cement plug at surface.
9. Rig wellhead for abandonment and install marker.

NOTE: Drinkard is east casing
Blinebry is west casing
Follow each cement plug with gelled mud.

NO AFE - Charge LC-652.



S.E. Barker

HNS/sm
6-26-72

SUBJECT

PREPARED BY

DATE

DEPARTMENT

PAGE

HNS 4-24 12

BOWERS "A" FEDERAL No. 32

