

BRIDGES STATE # 183
VACUUM (WOLFCAMP) FIELD
LEA COUNTY, NEW MEXICO

RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. RIH W/ WS TO 9900'. LOAD HOLE W/ 10 PPG GELLED BRINE.
3. PUH TO 6201'. SPOT 25 SX CLASS C NEAT CMT PLUG ACROSS GLORIETA TOP @ 6101' FROM 6201-6001'.
4. PUH TO 4900'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS CSG SHOE @ 4850', GRAYBURG SAN ANDRES TOP @ 4665' & TOL @ 4655' FROM 4900-4600'.
5. PUH TO 3010'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS YATES TOP @ 2954' FROM 3010-2880'.
6. PUH TO 1860'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @ 1808' FROM 1860-1730'.
7. PUH TO 415'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS CSG SHOE @ 350' FROM 415-285'.
8. PUH TO 30'. SPOT 15 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
9. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.