

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYCOPY TO O. O. O.  
SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved  
Budget Bureau No. 42-R1424

LEASE DESIGNATION AND SERIAL NO.

NM 9560-A

G. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Inexco Oil Company

3. ADDRESS OF OPERATOR

1100 Milam Bldg., Suite 1900 Houston, Texas 77002

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surfaceSW 1/4 - NE 1/4  
1980 FNL & 1980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether of, to, or from)  
3656.5 gr

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) see below

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Perf Strawn 12,326-370 2 SPF. Acidize Strawn 12,326-370' with 2000 gal 15% acid NEFE  
Run GR & Otis blanking plug - set in 'X' nipple @12,290'. Run and set Halliburton EZ  
Bull Plug at 12,200'.

This plugs off Strawn and Morrow perfs. Run and Set Baker Model 'D' pkr. at 11,150'.  
Perf Wolfcamp 12,264-12,314', 64 holes. Acidize Wolfcamp 12,264-12,314 with 4000 gal  
Mod 202 acid. Run and set blanking plug in 'N' nipple at 11,165'. This plugs off  
Wolfcamp perfs. Perf L. Bone Springs 10,312-318' w/4 spf. Acidize L. Bone Springs  
10,312-318' with 1000 gal 15% NEFE acid. Run Howco 5 1/2" CIBP and set @10,250'.  
This plugs off Lower Bone Springs. Perf. Upper Bone Springs @10,084-10,118', 17 holes.  
Acidize Upper Bone Springs 10,084-118' with 2500 gal 15% NEFE acid. Run 326 jts. and  
Baker Lockset Pkr. set @9950'.

Pull 326 jts. and Baker Lockset Packer from 9950'. Drill out Howco 5 1/2" CIBP at  
10,250'. Mill out Baker Model 'D' Pkr. and Junk at 11,150' and 11,165' and push to  
12,200'. Halliburton EZ Bull Plug. This opens up Wolfcamp perfs. 12,264-314' and  
Lower Bone Springs perfs. 10,312-18' and Upper Bone Springs perfs. 10,084-118'.  
Perforate additional Wolfcamp zones @10,901-907', 11,181-208', 11,218-224', 11,236-  
240', 11,328-330', and 11,362-368' with 51 holes.  
Acidize Wolfcamp 10,901'-11,368' w/8000 gal 15% NEFE acid.

Put well on pump @10,000' ± seating nipple with Bone Springs and Wolfcamp zones  
commingled.

18. I hereby certify that the foregoing is true and correct

SIGNED Karen PalmquistTITLE Production ClerkDATE 10/16/79

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

AR Hall  
OCT 20 1979U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

See Instructions on Reverse Side