

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fed <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-4883	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator Amoco Production Company		8. Farm or Lease Name State HR	
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240		9. Well No. 2Y	
4. Location of Well UNIT LETTER <u>A</u> <u>380</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Airstrip Lower Bone Spr.	
15. Elevation (Show whether DF, RT, GR, etc.) 3954.9' GL		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the subject well per the following:

Move in service unit and pull tubing and packer. Run in hole with a cast iron bridge plug and set CIBP at 9200'. Spot 35' of class "C" neat on top (approx. 3.5SX). Pull up and spot 127 bbls of 10# brine with 25# gel/bbl. Pull up and spot 25 sx class C neat across 9-5/8" casing shoe at 4000'. WOC. Tag top of cement plug. If cement plug is 50' above the 9-5/8" casing shoe proceed with next step. If not, spot enough cement so the top is 50' above the 9-5/8" casing shoe. Spot 50 bbl of 10# brine with 25# gel/bbl. Run free point to determine top of cement behind 5-1/2" casing. Cut casing 1 jt. above top of cement. Pull casing. Spot 100 sx of class "C" neat across 5-1/2" casing cut point. WOC. Tag top of cement plug. If the plug is 50' above the 5-1/2" casing cut point, proceed with next step. If not, spot more cement. Spot 108 bbls 10# brine with 25# gel/bbl. Spot 115 sx class "C" neat from 352' to surface. Weld on cap and erect permanent abandonment marker.

\* Notify NMOCD prior to setting plugs.

0+4-NMOCD,H 1-HOU 1-F. J Nash, HOU 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Herring TITLE Assist. Admin. Analyst DATE 3-31-83

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

MAR 5 1983

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 4 1983

O.C.D.  
HOBBS OFFICE