

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

API No. 30-025-27995

|   |                              |
|---|------------------------------|
| 5a. Indicate Type of Lease                |                              |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br>B-2148    |                              |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Phillips Petroleum Company

Address of Operator

Room 401, 4001 Penbrook, Odessa, TX 79762

Location of Well

UNIT LETTER K 2130 FEET FROM THE South LINE AND 1980 FEET FROM

THE West LINE, SECTION 22 TOWNSHIP 17-S RANGE 33-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Leamex

9. Well No.

35

10. Field and Pool, or Wildcat

Maljamar Gb/SA

15. Elevation (Show whether DF, RT, GR, etc.)

4149' CR, 4161' DF

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER Abandon Paddock & Recomplete ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Procedures are as follows:

1. MI DD well service unit and BOP.
2. If necessary, kill well with 2% KCL water
3. Pull rods and pump.
4. Install BOP and pull tubing.
5. GIH w/cast iron bridge plug. Set at 5000'. Dump 2 sxs cement on BP. Load hole w/2% KCL FN. Press test to 3000 psi.
6. Spot 3 bbl of 10% acetic acid 4800'-4950', and COOH with tubing.
7. Phillips supervisor to hold safety meeting. McCullough to install a 3000 psi lubricator. Test lubricator to 1000 psi and perforate the 4 1/2" OD casing from top to bottom with deep penetrating charges and 2 JSPF with spiral phasing from 4886'-4890' 4', 8 shots and from 4904'-4918', 12', 24 shots.
8. GIH with a RTTS-type packer on 2 3/8" tubing. Set packer @4850'. Swab perfs to clean up.
9. Load csg./tbg. annulus with 2% KCL water and pressure test csg. and packer to 1000 psi. Hold test pressure during the following acid treatment.
10. Dresser Titan to acidize perfs, 4886' to 4918' down 2 3/8" OD tubing with 2000 gallons (48 BBL) 20% NEFE HCL acid at 5-6 BPM with 1-1.3 S.G. ball sealer in each 50 gallons

(See reverse side)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BOP Equip: Series 900 3000# WP, double w/1 set pipe rams, 1 set blind rams manually operated.

SIGNED W. J. Mueller TITLE Sr. Engineering Specialist DATE July 29, 1983

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 4 1983

CONDITIONS OF APPROVAL, IF ANY:

10 10 10 10 10 10 10 10 10 10

RECEIVED

AUG 1 1983

O.C.D.

HOBBS OFFICE

- acid. Do not exceed 40 ball sealers. Flush with 35 BBL 2% KCL water. Maximum treating pressure: 5000 psi.
11. Swab back load and COOH with packer and tubing.
12. GIH with tubing, tubing anchor, and seating nipple. Set seating nipple on bottom @ 4950' w/tbg. anchor @ 48500 in 100 lbs tension.
13. Return pump and rods. Return well to production.