N. M. SIL GENS. COMMISSION P. O. BOX 1880

Form 9-331 Dec. 1973

 $5\frac{1}{2}$ csg.

P. O. BOX 1990 HODAS, NEW MEXICO 88240

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR NM 12412 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 8. FARM OR LEASE NAME Sloan Federal 1. oil gas well well other Dry hole 9. WELL NO. 2. NAME OF OPERATOR 2 Sun Exploration & Production Co. 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR East Lusk (Wolfcamp) P.O. Box 1861, Midland, Texas 79702 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 990' FNL & 1980' FEL <u>Sec. 22, T-19-S, R-32-E</u> 12. COUNTY OR PARISH 13. STATE Unit Ltr. "B" AT TOP PROD. INTERVAL: Lea NM AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING change on Form 9-330.) MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 5-3: MIRU Caffey csg pullers, cln out cellar, Install matting boards, rig up unit. 5-4: Nipple dwn well head, Install BOP, Lower tbg to 10,750, Mix & load hole w/ 120 bbls, 10# salt gel mud, Spot 50 sxs class "H" cmt plug 10,750-10,310 Raise 2-7/8 tbg to 8250. 5-5: RIH w/ 2-7/8 WS tag cmt plug @ 10,285, POH w/ 2-7/8 WS, cln out cellar, nipple dwn BOP & $5\frac{1}{2}$ well head, cut & weld on lift sub, Rig up csq jacks. 5-6: Install csg jacks, remove slips, work csg $3\frac{1}{2}$ NRS, ran free DT on WL, Indicated 100% stuck 7455, 100% free 7390.

5-8: Jet cut $5\frac{1}{2}$ csg @ 7400', jack & pull 2 jts, csg pulled free, lay dwn 180 jts,

5-9: Rig dwn csg jacks, NU BOP & well head, RIH w/ 2-7/8 WS open end to 7470. Spot 50 sxs class 'H' cmt plug 7470-7253, POH w/ 2500' 2-7/8 WS, WOC.

MAY RECEIVED