Form 3160-5 June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR FERMIT—" for such proposals

SUBMIT IN TRIPLICATE

If Unit or CA. Agreement Designation

Type of Well		
X Oil Gas - Other		3 Well Name and No.
2. Name of Operator		French Federal No. 1
Marathon Oil Company		- API Well No.
Address and Telephone No.		30-025-29623
P. O. Box 552, Midland, TX 79	9702 (915) 682-1626) Field and Pool. or Exploratory Area Querecho Plains
+ Location of Well (Footage, Sec., T., R., M., or Survey Des	cription	(Delaware)
660' FSL and 660' FWL		County or Parish, State
Section 24, T-18-S, R-32	-Е	Lea, NM
CHECK APPROPRIATE BOX(s	TO INDICATE NATURE OF NOT	ICE, REPORT. OR OTHER DATA
TYPE OF SUBMISSION	ŢŸ₽	E OF ACTION
X Notice of Intenx		- Change of Plans-
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Rousse Fracturing
	Casing Repair	Water Shan-Off
Final Abandonment Notice	Altering Casing	Conversion to injustion-
	Other	Dispose Water
		Note: Report results of comparison on Wet Compassion or Recomplation-Report and Log form.)

13. Describe Proposes or Completes Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If web's directionally drilled give substrikes locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Marathon Oil Company respectfully requests permission to recomplete from the Querecho Plains (Bone Spring) to the Querecho Plains (Delaware) as outlined:

(See attachment)

14 Thereby certify mature integrand is true and correct Signed And Rod J. Prosceno	Tide Operations Engineer	Date
String	Tide	Date 3/16/92
Title 18 U.S.C. Section 1001, masses is a crime for any person knowingsy	and welfelly to make to any departments or agency of the United States.	ary mise. Schlimmer franchisen stationen
or representations as to any statute within its jurisdiction.		

FORM APPROVED Budget Burger No. 1004-0135 Expires: March 31, 1993

S Lesse Designation and Serial No.

№**M**-2945

2 if Indian, Autome or Fribe Name

RECOMPLETION PROCEDURE

FRENCH FEDERAL NO. 1 660' FSL and 660' FWL Section 24, T-18-S, R-32-E Lea County, New Mexico

AFE No.: 6174 Date: February 14, 1992 Purpose: Recomplete from the Bone Spring to the Delaware Formation. Elevation: GL: 3,777' KB: 3,789' TD: 8,700' PBTD: 3,622 Subsurface Casing: 11-3/4, 42#. H-40, ST&C set @ 350', amt'd w/725 sx Class "C" w/2% CaCl. Circ 125 sx to pit. Intermediate Casing: 8-5/8", 24#, K-55, S-80, ST&C set @ 2,800' (2,200'/600'). Imt'd w/1,500 sx lite 3 and 500 sx Class "C" w/2% CaCl. Circ 200 sx to pit. Production Casing: 4-1/2", 11.6#/10.5#/11.6#, K-55 ST&C set @ 8,700' (1,400'/5,300'/2,000'). Cmt'd w/600 sx lite 3 and tailed in w/180 sx lite 5 (Dowell). Good returns. TOC @ 4,780'. Perforations: Bone Spring 8,534'-8,544' and 8,561'-8,568' w/1 SPF (19 holes). <u>Tubing</u>: 2-3/8", 4.7#, N-80 (189 Jts), MA 4' perf'd sub, SN, 5 jts, 2-3/8", N-80, TAC, 184 jts, 2-3/8", N-80, 1 - 10' and 1- 8', 2-3/8" sub. Set TAC @ 8,456' w/12,000# tension. Bottom MA @ 8,645', SN @ 8,609'. E.ods: 1 - 2' X 3/4" sub, 237 - 3/4" rods, 103 - 7/8" rods, 1 - 6' x 7/8" sub. Fressure Data: Static bottom hole pressure - Bone Spring: 1,730 psi Delaware: 1,600 psi Safety: Bone Spring: H₂S - 200 PPM Delaware: H2S - 1,800 PPM

- 1. Test safety anchors to 22,500 lbs. MIRU PU.
- 2. Bleed down pressure from tubing and casing.
- 3. Install rod stripper. Pull out of hole with rods and pump.
- 4. Nipple up 6" Series 900 BOPs with 2-3/8" pipe rams.
- 5. Release TAC and POH w/2-3/8" tubing.
- 6. RIH w/4-1/2" cup type RBP and 4 stand of 2-3/8" tubing. (Note: Use production string as the workstring.) Set RBP and POH. Load hole w/2% KCl water. Close blind rams and test to 2,000 psi. Open blind rams.
- 7. RIH w/4-1/2" tension packer and 3 stands of 2-3/8" tubing. Set packer.
- 8. NU TIW value on 2-3/8" tubing and close value. Close pipe rams and test to 2,000 psi. Open pipe rams, ND TIW value and POH.
- 9 RIH w/retrieving head on 2-3/8" tubing. Retrieve RBP and POH.
- 10. Rig up wireline company. RIH w/4-1/2" CIBP on wireline to 8,450'. Get on depth and set CIBP @ 8,450'. POH w/wireline.
- 11. Run CBL and base gamma ray/temperature log from 5,000' to 7,000'. POH w/wireline tools.
- 12. RIW w/3-1/8" casing guns and perforate the Delaware from 6,650' to 6,670' w/2 SPF (40 holes). POH and rig down wireline company.

RECEIVED

MAR 1 9 1992 CO HOBBS CTER FECOMPLETION PROCEDURE FRENCH FEDERAL NO. 1 Lea County, New Mexico Cage No. 1

- 13. RIH w/RTTS and 2-3/8" tubing to 6.670'.
- 14. Rig up service company. Spot 250 gals of 15% HCl acid. Pull up to 6,550' and reverse 4 barrels. Set packer and slowly pump spot away.
- 15. Release treating packer and spot acid to top of packer. Set packer and load backside. Pressure up and hold 500 psi on backside. Acidize Delaware with 1.750 gals 15% HCl acid. Flush to bottom perforation @ 6.670'. Rig down service company.
- 16. Rig up swab and swab test zone. (Note: Record swab test results and evaluate if zone should be fractured.)
- 17. POH w/4-1/2" treating packer and 2-3/8" tubing.
- 13. TIH w/2-3/8" tubing open ended to $\pm 6.500^{\circ}$.
- 19 Rig up service company. Conduct at lease 2 pump-in/flowback tests to determine closure stress as follows:

Pump 50 bbls of slick water 3 5 BPM for 10 minutes. Open flowback valve and flow well back at a rate of 1 BPM. Record pressure and rates. (Note: Should have 10,000 gals of slick water on location for test.)

20. Fracture stimulate the Delaware with 29,000 gal of delayed borate and 71,000# of 20/40 sand. The last stage of job should be 18,000 of curable resin coated sand. The fracture treatment should be pumped as follows:

VOLUME	PROP CONC.	PATE
10.000 Gals 2.000 3.000 5.000 4.000 3.000	.) ≠/Gal 2 3 + 5 6	10 13 12 12 12 12
	,	- 0

- 21. Rig down service company. Rig up wireline company. Ran after frac survey. Rig down wireline company. Shut well in over night.
- 22. Open well up and flow back load. Swab back load if necessary.
- 23. POH w/2-3/8" tubing. RIH w/2-3/8", 4.7#, N-80 tubing and TAC. Set TAC @ ±6,500'.
- 24. ND BOPs. NU wellhead.
- 25. FIH with a 1.5" pump, 177 3/4" and 91 7/8" rods (NABLA attached).
- 26. Hang well on.
- 27. RDMO PU. Start well pumping and place on test.

Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

1

DISTRICT (P.O. Box 1580, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL LOCATION AND ACREAGE DEDICATION PLAT

All Distances must be from the outer boundaries of the section

Operator				Lease					Well No.		
Marathon Oil Company			French Federal					1			
Unit Letter	Sectio		Township		Range			Cour	nty		
M	i	24	18-5	3	32-E					Lea	
Actual Footage Loca			10-3		<u> </u>		NM	PM			
-		-	~			0			T.T		
660	feet f		South	line and	66	0	feet fi	om the	West	ime	
Ground level Elev.		Producing	g Formation		Pool				-	Dedicated Acre	age:
3,777		Querecho	<u>o Plains</u>	(Delaware		laware				40	Acres
1. Outline	e the ac	reage dedicated	to the subject v	well by colored pe	ncil or hachure r	narks on the p	lat below.				
2. If more	e than c	one lease is ded	icated to the we	il, outline each an	d identify the ow	mership thereo	of (both as to w	orking inte	rest and r	oyalty).	
5. If more	e than c	ne lease of diff	erent ownership	o is dedicated to th	e well, have the	interest of all	owners been co	nsolidated	by comm	unitization.	
		rce-pooling, etc							,	··-,	
	Yes			answer is "yes" ty							
			and tract descr	riptions which have	e actually been c	onsolidated. (Use reverse sid	e of			
this form			- the mail matil	all interacts have b			***	. <u> </u>	:		
ce until a	non-eta	inder das signed under daring with the second se	ninating such in	all interests have b iterest, has been ap	recti consolidated	i (by commun	iuzauon, uniuza	uon, iorce	a-pooing	g, or otherwise)	
			intering south in								
[OI	PERAT	OR CERTIFI	CATION
		!				!		1			he information
		1									complete to the
						1				edge and belief.	•
		i				Ì				1	
		i				1		Signatu	MY N/		
		-				t r			Kod !!	lower	-
		ļ						Printed	Name		
										magana	
								Position		Prosceno	
		İ				Ì			-	na Durin	
		i		ł		1				ons Engin	eer
						i I		Compa	•		
								Mai	rathor	n Oil Com	pany
								Date			
		1						2/2	28/92	-	
			<u>.</u>			 		SURVEYOR CERTIFICATION			ICATION
				1		, 		1		· • • • •	In and in a
						1					location shown field notes of
											or under my
											ve is true and
		1				1					knowledge and
		i				i	1	belief.			5
										•	
						1	an Personal	Date S	Surveyed		
				-+		<u>+</u>					
F								Signat	ure & Sea sional Su	l of	
[.								PTOIES	MONIAL SUI	veyor	
		Ì				1		1			
660		i				İ					
F		1									
60	60'	1				1					
i ot	00	Į				ļ		Certifi	cate No.	*	
		2									
								ļ			
0 330 660	990	1320 1650	1980 2310	2640 20	00 1500	1000	500 0				