

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Regency Petroleum Company of New Mexico	8. Farm or Lease Name State 32
3. Address of Operator 600 E. Carpenter Suite 255 Irving, Texas 75062	9. Well No. 1-B
4. Location of Well UNIT LETTER <u>B</u> <u>350</u> FEET FROM THE <u>North</u> LINE AND <u>350</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>18S</u> RANGE <u>39E</u> N.M.P.M.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up unit and equipment.
2. Lay down rods & pump.
3. Pick up tubing and tag C.I.B.P. @ 5825'. Pump mud from 5825' to 4300'.
4. Spot 5 sks. of cement on top of C.I.B.P.
5. Pull tubing to 4300' and spot 25 sks. of cement and wait on cement.
6. Attempt to tag and could not. Spot 25 sks. of cement with w/2% Calcium Chloride @ 4300'.
7. Wait on cement 2 hours. Attempt to tag and could not. Spot 25 sks. of cement w/ 2% Calcium Chloride @ 4300'.
8. Wait on cement 2 hours. Tag plug @ 4190'. Circulate hole with mud.
9. Pull tubing to 3010'. Spot 25 sks. of cement.
10. Pull tubing to 1864' and spot 25 sks. of cement.
11. Lay down tubing, dig cellar, cut off wellhead, spot 10 sk. surface plug, install P & A marker.
12. Rig down unit and equipment, cut off anchors, clean location. Road unit and equip. to yard.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Dale May</u>	Dale May	TITLE <u>Baber Well Service P & A Supervisor</u>	DATE <u>3-17-87</u>
APPROVED BY <u>R. A. Hall</u>		TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 31 1987</u>
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED
MAR 20 1981
HOBBS OFFICE