Form 3	160 5		HAD D CTA	TEC	SUBMIT IN TRIPL	7E•	Form approv	au No.	
Novem	7 - 1		UN) .D STA MENT OF TH	E INTERIO	/ Oak !	re-	Expires Aug  5. LEASE DESIGNAT		
		BUREA	AU OF LAND MA	NAGEMENT			NM 26884-E	WTT 00	MAINT WAYE
	SUND (Do not use this fo	RY NOT	ICES AND R	EPORTS C eepen or plug ba c—" for such pro	N WELLS  ck to a different reservoir  pposals.)		O. IF INDIAN, ALLO.	TAR OR	IRIDE NEXE
1. SAB C Comporarily Abandoned							7. UNIT AGREEMENT NAME		
WELL WELL OTHER TENDOLETLY ADMICOIRED  2. NAME OF OPERATOR							8. FARM OR LEASE NAME		
OXY USA Inc.							Federal AG		
3. ADDRESS OF OPERATOR P. O. Box 50250, Midland, TX 79710							2		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface							Central Corbin Queen  11. SEC., T., E., M., OR BLK. AND		
231	0' FML & 330	)' FELL					Sec.8-T18S-	LWA	
14. PERMIT NO.			15. ELEVATIONS (Show whether DF, RT, CR, etc.)				12. COUNTY OR PAR		STATE
	025-30326		3924' GR				<u>Lea</u>		NJW.
 16.	02.110.120	Check A		o Indicare No	ature of Notice, Repor	rt, or O	ther Data		
	Check Appropriate Don to manage of the second of the secon						QUENT REPORT OF:		
	ST WATER SHCT-OFF		PULL OR ALTER CASIS	NG	WATER SHUT-OFF		REPAIRIN	G WELL	
	CTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMEN	T	ALTERING	CABING	!
	OUT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZE	ING	ABANDON	MENT*	X
REF	AIR WELL		CHANGE PLANS		(Other) Report	results (	of multiple completic	n on W	ell
	ther)		Charte eta	th all pertinent	Completion or	Recomple	ncluding estimated	form.)	starting any
p ne	roposed work. If w ent to this work.) •	ell is directi	onally drilled, give s	unnuriace locatio	ons and measured and tru-	e rettiens	depths for all mark	ers and	gones perti-
Thi	s well was p	oLugged	and abandone	с ш шел	following manner	•			
1.	MIRU pull @ 4200'.	ing un Dumpe	it, POOH w d 3 sacks	/tbg. & of cemen	packer. RU N t from 4 <b>7</b> 00'	to 4;	set a 5-1/ 150' on to	2" C. p of	IBP plug.
2.	2. RIH w/2-3/8" OE'd tbg. to 4104' and press. csg. to 1000#. Circulate the hole w/9.5 ppg. mud laden fluid. POOH w/tbg. to 3214'.								
3. Spotted 15 sacks cement plug across 3214'-3114' 1/2 in and 1/2 out of 8-5/8" csg. shoe @ 3175'. POON w/tbg.									
4.	4. Ran free point on 5-1/2" csg., found free @ 1450'. Cut csg. @ 1450' and POOH.								
5.	20 sacks cmt. plug @ 1500' to 1400', 1/2 in and 1/2 out of 5-1/2" csg. @ 1450'.								
6.	RIH w/2-3 sacks cmt	3/8" OE	o'd tbg. T g from 415'	ag plug to 315	@ 1377'. PCC '.	OH to	415'. Sp	otte	d 30
						(	Cont'd on	Page	2)
	reby certify that the	tano	is true and correct	TITLE Dis	t. Oper. Mgr.	- P	rod DATE 10	-27-	88
	is space for Federa	l or State of	ice use)						
	ROVED BY			TITLE			DATE	1.8	* \$ <b>5</b>
CON	NDITIONS OF APP	ROVAL, IF	ANY:						

\*See Instructions on Reverse Side