

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30949 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-4087
7. Lease Name or Unit Agreement Name State 16
8. Well No. 6
9. Pool name or Wildcat West Corbin (Delaware)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3863

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Meridian Oil Inc.	3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	4. Well Location Unit Letter O : 660' Feet From The South Line and 1890' Feet From The East Line Section 16 Township 18S Range 33E NMPM Lea County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Stimulate ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU pulling unit. ND pumpin tee. POH with rod string and pump. Kill well with 2% KCl water containing 2 gpt of TFA-380B (Surfactant) from Dowell. ND wellhead. NU BOP. Release TAC and POH with production tubing.
- RIH with a bit and scraper for 5 1/2" 15.5 casing to PBTD of 5445'. POH.
- RIH with PCT and 2 7/8" tubing to the top set of perfs at 5090-5097'. NU BIW stripper head and enough chicksans and steel line necessary for tool movement across the perforated intervals.
- MIRU stimulation company. NU surface lines and test to 4000 psi Monitor the 2 7/8" X 5 1/2" annulus. Pump the following volumes of AE aromatic across the various perforation intervals listed below. Allow chemical to soak for approximately 24 hours. On the following day, pump the following volumes of Pentol 250 (7 1/2% NEFE HCl acid) across the various perforation intervals.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE Production Assistant DATE 5-17-93
TYPE OR PRINT NAME Donna Williams TELEPHONE NO. 915-688-6943

(This space for State Use)

ORIGINAL FILED BY JERRY SEXTON
EXTENSION 1 SUMMER 1993

MAY 19 1993

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 10 1993

OCD HCBBS OFFICE

State "16" No. 6
West Corbin (Delaware) Field
Lea County, NM

<u>Perfs</u>	<u>AE Aromatic Volume</u>	<u>Pentol 250 Volume</u>
5090-5097'	175 gals.	700 gals.
5117-5121'	100 gals.	400 gals.
5194-5198	100 gals.	400 gals.
5213-5220'	175 gals.	700 gals.
5225-5231'	150 gals.	600 gals.
5236-5245'	225 gals.	900 gals.

Reciprocate the PCT across the perforations while pumping both fluids. Flush with 2% KCl water containing 2 gpt of TFA-380B or Acid Engineering's equivalent.

Anticipated Treating Rate	= 2 BPM
Anticipated Treating Pressure	= 1000 psi
Maximum Annular Pressure	= 1500 psi
Maximum Treating Pressure	= 3900 psi

POH with tubing . RDMO stimulation company.

5. RIH with SN, tubing anchor, and 2 7/8" tubing. Set anchor at previously set depth. ND BOP. NU wellhead. RIH with pump and rpd. Space out pump and connect to pumping unit. RDMO pulling unit.

6. Connect to surface facilities and begin pumping. Report rates to the Midland office.

RECEIVED

MAY 10 1993

OCD HOBBS 07111