

**South Corbin Federal No. 3  
Corbin (Yates) Field  
Lea County, New Mexico**

Project Engineer: **D.J. Chapman**

Office (915) 688-6987  
Residence (915) 694-5232

**Recommended Plug and Abandonment Procedure**

**Note: Notify BLM prior to any plugging operations.  
H2S may be present**

Top of Salt: 2850'

Base of Salt: 4450'

1. Move in +/- 10800' of 2-7/8", 6.5 lb. ft., N-80 workstring to location.
2. MIRU pulling unit. Install and test BOPE. POOH laying down 3-1/2", 9.3 lb/ft, N-80 HYDRIL tbg.
3. GIH w/ 5-1/2" CIBP on 2-7/8", 6.5 lb/ft, N-80 tubing setting CIBP @ 10650'. Circulate hole w/10 ppg gelled brine mud. Cap w/ 25 sx (250') Class C cement plug.
4. Pick up tubing to +/- 9800'. Spot 25 sx (250') Class C cement plug.
5. Pick up tubing to +/- 9500'. Spot 25 sx (250') Class C cement plug.
6. Pick up tubing to +/- 8650'. Spot 25 sx (250') Class C cement plug.
7. Pick up tubing to +/- 7400'. Spot 25 sx (250') Class C cement plug.
8. Pick up tubing to +/- 5100'. Spot 25 sx (250') Class C cement plug.
9. Pick up tubing to +/- 3042'. Spot 25 sx (250') Class C cement plug. POOH w/tubing.
10. RU wireline company and packoff. GIH w/casing cutter and cut casing at free point estimated to be at 2350' by CBL. POOH and lay down casing.
11. RIH w/2-7/8" tubing open ended to 2442'. Spot 35 sx (96' in 5-1/2" & 96' in 8-5/8") Class C cement plug.
12. Pick up tubing to +/- 545'. Spot 35 sx (130') Class C cement plug.
13. Pick up tubing to +/-130'. Spot 35 sx (130') Class C cement plug to surface.
14. Cut off casing 3' below surface. Weld steel plate and abandonment marker to casing stub. Restore location as directed.

Approved: \_\_\_\_\_  
H. A. Lee

Date: \_\_\_\_\_