-89

Submit 3 copies to Appropriate District Office	Enen linerals and Natura	al Resources Department	-	Revised 1-1-
	OIL CONSERVAT	TION DIVISION	WELL API NO.	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box		30025320	109
DISTRICT II			Indicate Type of Lease	
P.O. Box Drawer DD, Artesia, NM 88210	Santa Fe, New Me	XICO 07304-2000	ST	ATE FEE
DISTRICT III			6. State Oil / Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.		7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SAN ANDRES UNIT		
1. Type of Well: OIL GAS WELL WELL	OTHER			
Name of Operator TEXACO EXPL	LORATION & PRODUCTION I	NC.	8. Well No. 258	
3. Address of Operator 205 E. Bender	, HOBBS, NM 88240		Pool Name or Wildcat Vacuum Graybu	rg San Andres
4. Well Location				
Unit LetterA :	660 Feet From The	NL Line and 510	Feet From The_EL	Line
Section 1	Township 18-S	Range 34E N	MPM LI	EA COUNTY
	10. Elevation (Show whether DF,	RKB, RT,GR, etc.) D.F 4005	, K.B. 4006	
11. Check Apr	propriate Box to Indicate	Nature of Notice, Report	t, or Other Data	
• •	•		UBSEQUENT REPC	DT OE:
NOTICE OF INTENTION			-	_
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	✓ ALTERING (
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PERATION PLUG AND A	ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEME	NT JOB	
OTHER:		OTHER:	ACID FRAC	
 12. Describe Proposed or Completed Oper proposed work) SEE RULE 1103. 5-04-00: MIRU. NDWH. NUBOP. WORK 5-05-00: RAN FP. TAG @ 4523'. FP @ 4 	ON STUCK PUMP. RAN STRI	ETCH. PUMP 200 BW DN CS	G. WRK STUCK PUMP.	
4488'. 5-08-00: TIH W/WL SPEAR, BS, & TBG. SUB, & TBG. TAG @ 4488'. MILL 4488-4- 5-09-00: REDRESS OVERSHOT. TIH W/	TAG @ 4488'. WRK TO 4494' 494. LATCH ONTO FSH. JAR.	TIH W/MILL GUIDE, OVERS	HOT W/EXTENSION, BS, J	
5-10-00: TIH W/JARS, DC'S & TBG. TAG 4016'.	G @ 4597'. WASH 4597-4600.	CUT FISH NECK 4600-4602.	TIH W/SPECIAL JOINT, JAF	RS, DC'S & TBG TO
5-11-00: TAG @ 4601'. WASH 4601-4608 5-12-00: TIH W/OVERSHOT, BMPR SUE JARS. DC'S TO 4016'.	8. PULL PIPE TO 4015'. B, JARS, DC'S & ACCEL SUB.	LATCH ON FSH @ 4601'. JA	R. REDRESS OVERSHOT.	TIH W/BMPR, SUB,
5-15-00: KILL W/50 BFW. LOWER TOOL OVER FISH 4601-09'. C/O BOP. TIH W/B 5-16-00: KILL W/50 BFW. LATCH ONTO 5-17-00: TIH W/SAME.	BOX TAP, BMPR SUB, DC'S O	N TBG TO 4003'.	HT JT, JARS, DC'S ON TBO	3 TO 4601'. CUT
5-18-00: TIH TO 4712'. 5-19-00: LOWER TBG & TOOLS & TAG 5-20-00: PSA 4194'. INSTL FRAC TREE 5-22-00: PERFORM CO2 FOAM ACID F TONS CO2.	ON TOP OF BOP & TEST TO FRAC ON PERFS 4284-4690 V	1000#-OK.HU BLOW DN LIN	E TO FRAC TANK.	
5-24-00: ND FRAC TREE. REL PKR. TIH 5-25-00: TIH W/MOTOR, GAS SEPR, PN ON 24 HR OPT. PUMPED 47 BO, 836 BV	MP, SUB. MOTOR @ 4277". N	DBOP. NUWH. PLACE ON PU T	JMP 3:00 PM. RIG DOWN.	

I hereby certify that the info **Engineering Assistant** DATE 6/19/00 SIGNATURE 397-0405 Telephone No. J. Denise Leake TYPE OR PRINT NAME (This space for State Use) ------ 30n **APPROVED** _TITLE DATE BUNDITIONS OF APPROVAL, IF ANY: DeSoto/Nichols 12-93 ver 1:0