New Mexico Oil Conservation Division

1625 French Drive, Hobbs, NM 88240

Energy, Minerals and Natural Resources Department

2040 South Pacheco, Santa Fe, New Mexico 87505



Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

16-Nov-99

BURLINGTON RESOURCES OIL & GAS CO

PO BOX 51810 MIDLAND TX 79710-

Dear Sirs:

Following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines as established by the U.S. Environmental Protection Agency, the well must me shut-in immediately until the well is successfully repaired. The test detail section which follows, indicates preliminary findings and/or probable causes of the failure. Please keep in mind that this is a subjective determination based on one or more factors of the results of the test. The actual malfunction may not be similar in nature to those as estimated by this testing. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division as to the date and time that repairs will be attempted so such operations may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

Well Type and StatusLocation Well Name and Number

API Well No.

EAST CORBIN DELAWARE UNIT 009

H 21 18S 33E Violation?

30-025-32915-00-00

Type of Inspection

Inspector

holding.

106

Inspection No.

*Significant Non-Compliance?

MW

iSAD0003184 e corb del ut #9. 21-18-33. Rigging back up. Pkr not holding from recent workover. Will reschedule

No

No

Comments on Inspection:

test. Tp ok. Constant water flow off csg. 2 pkrs dnhole to inj into lower zone. Top pkr apparently not Actual PSI: 1610 **Permitted Injection PSI:**

11/2/99 8:45:05 **Test Date**

Test Reason: ANNTST

Test Result:

Repair Due: 2/5/00 8:06:10 A

Test Type: BTST FAIL CAUSE: UNKNOWN

FAIL TYPE PKR

Comments on MIT:

recently workover to get pressure increase. Pkr not holding. Will rig back up. Left open. 2 pkrs downhole to inject into lower zone. Top pkr apparently not holding.

Thank you for your prompt attention to this matter and your efforts in helping to protect our ground water resources.

Sincerely.

Chris Williams, District I Supervisor

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.