## A. Emergency Procedures

- 1. In the event there is any evidence of H2S levels above 10 ppm, take the following steps immediately:
  - a. Secure breathing apparatus.
  - b. Order non-essential personnel out of the danger zone.
  - c. Take steps to determine if the H2S level can be corrected or suppressed, and if so, proceed with normal operations.
- 2. If uncontrollable conditions exist, proceed with the following:
  - a. Take steps to protect and/or remove any public downwind of the rig including partial evacuation or isolation. Notify necessary public safety personnel, New Mexico OCD District Supervisor, and the contract safety personnel.
  - b. Remove all personnel at the wellsite to the upwind safe briefing area.
  - c. Coordinate with public safety personnel for setting up and maintaining roadblocks.
  - d. Determine and proceed with the best possible plan to regain control of the well. Maintain tight security and safety procedures at all times until operations have returned to normal.
- 3. Responsibility:
  - a. The Cross Timbers approved supervisor shall be responsible for the complete implementation of the plan.
  - b. The Cross Timbers approved supervisor will be in complete control during any emergency situation.
  - c. The Cross Timbers approved supervisor shall designate a back-up supervisor in the event that he is not available.

## B. Emergency Reaction Steps

- 1. Drilling, Tripping, Running Casing, or Plugging
  - a. All Personnel
    - When the alarm sounds, don escape pack and report to the upwind safe briefing area.
    - Check status of other personnel (buddy system) to ensure that all personnel at the wellsite are accounted for.
    - Secure breathing apparatus.
    - Await orders from the Cross Timbers approved supervisor.
  - b. Drilling Foreman
    - Report to the upwind safe briefing area.
    - Don breathing apparatus and return to the point of release with the toolpusher or driller (buddy system).
    - Determine the H2S concentration.
      - Assess the situation and take appropriate control measures.