Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		•		Itto Bed I I O
DISTRICT 1 P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATIO		WELL API NO.	
P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St. <u>DISTRICT II</u> Santa Fe, NM 87505		30-025-33659		
P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE	X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	LAI FEE
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
			Silverstrand State	
1. Type of Well: OIL GAS WELL X WELL	OTHER			
2. Name of Operator			8. Well No.	
Marathon Oil Company			1	
3. Address of Operator P.O. Box 2409, Hobbs, NM 88240			9. Pool name or Wildcat Vacuum: Abo, North	
4. Well Location	•			
Unit Letter C: 660	Feet From The North	Line and198	Feet From The	West Line
Section 2	Township 17-S Ra	inge 34-E	имрм Lea	County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc		//////////////////////////////////////
		4049' KB 4068'	<i>\\\\\\\\\\</i>	
	ropriate Box to Indicate	1	-	
NOTICE OF IN	FENTION TO:	SUB	SEQUENT REPO	RT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
			[]	
TEMPORARILY ABANDON L CHANGE PLANS L COMMENCE DRILLING		OPNS. L. PLUG AND	ABANDONMENT [
PULL OR ALTER CASING L CASING TEST AND CEI			MENT JOB L	
OTHER: DO CIBP. Test Wolfcamp/	Abo for possible DHC X	OTHER:		
	oses to drill out the CIB	P at 8950° and test	t the Wolfcamp and Abo	o completions
	If economical, MOC will sus. Attached is a procedu			ium; Abo North
I hereby certify that the information above is tru				
SIGNATURE TILLY LOUR	/ TITI	LE Records Process	Or DATE	5/1/98
TYPE OR PRINT NAME Kelly Cook			TELEPHONE N	0.
(This space for State Use) ORIGINAL SIGNED B	Y CHRIS WILLIAMS		M	AV a
ORIGINAL SIGNED OF DISTRICT IS	UPERVISOR 	LE	DATE	4Y 04 1998

SILVERSTRAND NO. 1 660' FNL and 1980' FWL Section 2, T-17-S, R-35-E Vacuum North Field Lea Co., NM.

Date:

May 1, 1998

Status:

Abo Completion

Procedure:

Test Wolfcamp/Abo Completion

- 1. MIRU PU.
- 2. POOH w/ rods & pump.
- 3. ND wellhead. NU 5M psig hydraulic BOP w/ 2-7/8" pipe rams.
- 4. POOH w/ 2-7/8" production tbg.
- 5. PU & RIH w/ sand line drill on sand line.
- 6. Tag CIBP @ 8950'. DO CIBP and push below +-11,000'.
- 7. POOH w/ sand line. LD sand line drill.
- 8. RIH w/ 2-7/8" production tbg.
- 9. ND BOP. NU wellhead.
- 10. RIH w/ rods & pump.
- 11. Space as necessary. Load tbg and test pump action.
- 12. RDMO PU.
- 13. Return well to test for 1 2 months.
- 14. If the Wolfcamp/Abo completion is economical, submit DHC application. If the Wolfcamp/Abo completion is not economical, continue to step 15.
- 15. MIRU PU.
- 16. POOH w/ rods & pump.
- 17. ND wellhead. NU 5M psig hydraulic BOP w/ 2-7/8" pipe rams.
- 18. POOH w/ 2-7/8" production tbg.

- 19. PU & RIH 5-1/2" CIBP and RTTS pkr on 2-7/8" tbg.
- 20. Set CIBP @ +-8950'. Test CIBP to 500 psi.
- 21. POOH w/ tbg. LD RTTS pkr.
- 22. RIH w/ 2-7/8" production tbg.
- 23. ND BOP. NU wellhead.
- 24. RIH w/ rods & pump.
- 25. Space as necessary. Load tbg and test pump action.
- 26. RDMO PU.
- 27. Return well to test.
- 28. Submit the required NMOCD forms.

n:\regltory/commling/dhc/silvr_a