

ATTACHMENT

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103
Revised March 25, 1999

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02065

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-2354

7. Lease Name or Unit Agreement Name

State II

8. Well No.

1

9. Pool name or Wildcat

Vacuum; Grayburg-San Andres

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

Oil
Well ☐

Gas
Well ☐

Other **Injection**

2. Name of Operator

Mobil Producing TX. & N.M. Inc.

3. Address of Operator **P.O. Box 4358**

Houston

TX 77210-4358

4. Well Location

Unit Letter **P** : **660** Feet From The **south** Line and **660** Feet From The **east** Line

Section **22**

Township **17S**

Range **34E**

NMPH

Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

Additional Remarks

- 7/30/02 POOH LD 2-3/8" tubing. RIH w/ 4 stands from derrick. ND BOP. NU WH w/ 4' 2-3/8" sub on top. Test to 500 psi. Held, rig down unit.
- 7/31/02 MIRU change BOP rams, slips and elevators. ND WH, NU BOP. POOH w/ 59 stands, kill string. Pump 15 bbls fresh water down 5-1/2" casing. No returns from 8-5/8" casing. Oil on top of fluid in hole. RIH with 10 stands. SIFN.
- 8/01/02 Pump 25 bbls fresh water down tubing and out casing. POOH w/ tubing. Set packer at 60', test to 500 psi. Held. Oil coming to top. POOH w/ packer. Set RBP @ 185'. Dump 2 sxs sand, circulate clean. POOH, ND BOP. Pull WH. RU WLU, find casing collars at 7', 37' and 66'. Spear 5-1/2" casing. Back-off at 37'. Laid down spear. LD 5-1/2" casing. Fill up 8-5/8" casing with fresh water.
- 8/02/02 Open well up. PU 5-1/2" jt of casing, RIH and make up. Test to 500 psi. Wait on weather. Pull 20000 pounds over, set slips on 8-5/8" WH. Cap off. Welder cut off to length, weld on bell nipple. Test to 500 psi. Screwed on 5-1/2" WH. RIH w/ 3 stands. Circulate sand off packer. Retrieve RBP. RIH w/ tubing. SIFN.
- 8/05/02 Replace tubing. LD cylinder. POOH, LD 2-7/8" WS. RIH 10 jts 2-7/8" kill string. ND BOP. Pack off WH w/ 4' sub on top. RDMO WSU.
- 8/08/02 Ran MIT and charted.

