

BRIDGES STATE # 6 WIW  
VACUUM GRAYBURG (SAN ANDRES) FIELD  
LEA COUNTY, NEW MEXICO

RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. RELEASE 7" GUIBERSON UNI I TENSION PKR @ 2148'. POOH W/ PKR ON 69 JTS 2-3/8" RICE DUOLINE TBG & LD.
3. RIH W/ WS TO 4065'. LOAD HOLE W/ 10 PPG GELLED BRINE.
4. PUH TO 2852'. PUMP 35 SX CLASS C NEAT CMT PLUG FROM 2852-2752' ACROSS SALT BASE @ 2802'. POOH W/ WS.
5. RIH W/ PERF GUN ON WIRELINE TO 1791' & PERF 7" CSG. POOH W/ WIRELINE & PERF GUN.
6. RIH W/ PKR ON WS. SQUEEZE 50 SX CLASS C NEAT CMT PLUG FROM 1791-1691' ACROSS SALT TOP @ 1741'. **PLUG MUST BE TAGGED!**
7. PUH TO 826'. PUMP 35 SX CLASS C NEAT CMT PLUG FROM 826-726' ACROSS 10-3/4" CSG SHOE @ 776'.
8. PUH TO 30'. SPOT 15 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
9. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.