

WELL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BRIDGES STATE Well No. 6
Field: URQUIM (GRAC - S. D.)
County: LEA State: NEW MEXICO

RECOMMENDED PROCEDURE:

THE SAN ANDRES FORMATION WITH 1 JET SHOT PER PLANE
AS DIRECTED BY THE GEOLOGIST (U.L. INMAN, MIDLAND, TEX, EXT 328).

6. TREAT THE SAN ANDRES DEPOSITIONS WITH 1,000 GALS
OF THE FOLLOWING CLEAN-OUT SOLUTION:

A. 800 GALS OF XYLENE BOTTOMS.

B. 200 GALS OF 15% REGULAR, HCL ACID.

C. 2 GALS OF ADOFORM (10 GALS OF ADOFORM / 1,000 GALS OF ACID).

NOTE: BLEND THE ADOFORM INTO THE ACID PRIOR TO
MIXING THE ACID AND XYLENE BOTTOMS.

DISPLACE 800 GALS OF THE CLEAN-OUT SOLUTION
INTO THE FORMATION ALLOWING THE REMAINING 200
GALS TO SOAK THE FORMATION FOR 24 HRS.

7. SWAB AND CLEAN THE WELL OUT UNTIL ALL THE
CLEAN-OUT SOLUTION HAS BEEN REMOVED.

8. ACIDIZE THE SAN ANDRES DEPOSITIONS WITH 2,500
GALS OF 15% NON-EMULSION, IRON-STABILIZED, HCL ACID.
TREAT AT 3 TO 5 BBL/S/MIN AND INJECT A SUFFICIENT
QUANTITY OF RUBBER-COATED WASH BALL SEALERS TO
OBTAIN A COMPLETE BALL-OUT. APPROXIMATELY 45 BALL

8-8-73 JN

Oper. Engr.
Form - 1/73

Page 2 of 3.