

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02091
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT
8. Well No. 7
9. Pool name or Wildcat VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Texaco Exploration and Production Inc.	
3. Address of Operator P. O. Box 730 Hobbs, NM 88240	
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>24</u> Township <u>17-S</u> Range <u>34-E</u> NMPM LEA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4028' KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ADD PAY AND ACIDIZE FORMATION ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU, INSTALL BOP. PRESSURE TEST CSG TO 300 PSI FOR 30 MIN.
2. D/O CMT IN 4 1/2" LINER FR 6265'-6300'. SPT 40 GALS ACETIC AACID FR 6300'-6260'.
3. RUN GR/COLLAR LOG. PERF W/ 2 SPF FR 6260'-6290' (31 FT - 62 HLES)
4. SPT 50 GALS 20% NEFE FR 6260'-6290', SET PKR @ 6168', SQZ ACID INTO FORMATION. SI 1 HR, SWAB BACK, LOAD BS W/ FW.
5. A/ PERFS FR 6260'-6290' W/ 3000 GALS 20% NEFE HCL, MAX P = 3000#, AIR = 4 BPM. SWAB BACK LOAD, EVALUATE FOR TEST.
6. PERF W/ 2 SPF FR 6046'-6105' (60 FT - 120 HLES). SET RBP @ 6120', SPT 100 GALS 20% NEFE FR 6120'-6046'. SET PKR @ 5901', SQZ ACID INTO FORMATION, SI 1 HR, SWAB BACK, LOAD BS W/ FW.
7. A/ PERFS FR 6046'-6105' W/ 6000 GALS 20% NEFE HCL, MAX P = 3000#, AIR = 4 BPM. SWAB BACK.
8. TOH W/ RBP & PKR. PUT WELL ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 12-20-93

TYPE OR PRINT NAME MONTE C. DUNCAN

TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 23 1993

CONDITIONS OF APPROVAL, IF ANY: