AppropriateState of New Mexicoistrict OfficeEnergy, Minerals and Natural Resources Department				Form C-103 Revised March 25, 1999	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION DISTRICT II P.O. Box 2088			WELL API NO. 30-025-02093	Keviseu Maich 25, 1999	
Santa Fe, New Mexico 87504-2088				5. Indicate Type of	Lease STATE SFEE
1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV 2020 Serte Research Res NM 87505				6. State Oil & Gas I	
2040 South Pacheco, Sante Fe, NM 87505				8015	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)				7. Lease Name or U Bridges State	Jnit Agreement Name
1. Type of Well: Gas Oil Well Well Other					
Weil Weil Other INJ 2. Name of Operator 0 0 0 0				8. Well No.	
Mobil Producing TX & NM, Inc.				47	
3. Address of Operator P. O. Box 4358 Houston TX			-4358	9. Pool name or Wi Vacuum; Grayb	
4. Well Location		<u>.</u>	1090	1 <u></u>	
Unit Letter : 19	Feet From The South		Line and 1980	Feet From The	
Section 24	Township 17S			NMPH	Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			REMEDIAL WORK		ALTERING CASING \Box
TEMPORARILY ABANDON 🛛 CHANGE PLANS 🗆 COMMENCE DRILLI			NG OPNS.	PLUG & ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB \Box		
OTHER:			OTHER:		
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion) 					
Proposed TA Procedure: 1. MIRU. WSU. Blow off any pressure present. Lock and tag out all valves					
 ND wellhead and NU BOP and test. Release 7" Johnson Tension packer @ 4,060'. POOH with 2-7/8" tubing and 7" packer. 					
4. MIRU WLSU. PU and RIH with 7" CIBP on electric line. Set CIBP @ +/- 4,050'.					
5. PU and RIH with dump bailer on wireline. Dump bail 35' of cement on top of CIBP @ +/- 4050'. POOH with wireline and					
RDMO. 6. RIH with injection tubing to +/- 3500'. Pressure test annulus to 600 psi. If ok, circulate well with Baker Petrolite packer fluid.					
DOOL and low down 2 200' of 2 7/8" tubing Keen well full of fluid while trinning tubing Leave 300' of 221 string in the well					
Land tubing in the wellhead with a 4' x 2-7/8" tubing sub. 7. RD BOP and NU wellhead. Test casing to 600 psi. If OK, notify the NMOCD and schedule an official MIT test.					
 Land tubing in the wellhead with a 4' x 2-7/8" tubing sub. 7. RD BOP and NU wellhead. Test casing to 600 psi. If OK, notify the NMOCD and schedule an official MIT test. 8. Clean location. RDMO WSU. 					
					831-18050
I hereby certify that the information above is true and	complete to the best of my knowledge and b				
SIGNATURE D. D. D. Journal TITLE Sr. Regulatory Specialist					DATE 07/08/2002
TYPE OR PRINT NAME Dolores O. Ho	oward			TELEPHO	NE NO. (713) 431-1792
(This space for State Use)		_			
APPROVED BY		me	WINK		EX II MATE
CONDITIONS OF APPROVAL IF ANY:		GARY	W. WINK LD REPRESENTATIVE	11/STAFF MANAC	JUL 9 2002
5		OC FIC			\mathcal{A}