

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

U.S. CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02097
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name State G
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Mobil Exploration & Producing US, INC. Mobil Producing TX & NM Inc.* as agent for MPTM	8. Well No. #2
3. Address of Operator P.O. Box 633, Midland, TX 79702	9. Pool name or Wildcat Vacuum Grayburg (San Andre)	
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>24</u> Township <u>T17-S</u> Range <u>34-E</u> NMPM Lea County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐		SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐	
--	--	---	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP
- RIH W/ WS TO 2861'. LOAD HOLE W/ 10 PPG GELLED BRINE. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS SALT BASE @ 2811' AND TOC @ 2670' FROM 2861-2620'.
- PUH TO 1853'. CUT AND PULL 7" CSG OR PERFORATE AND SQUEEZE 50 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @ 1803' FROM 1853-1753'. **PLUG MUST BE TAGGED!**
- PUH TO 878'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS 10-3/4" CSG SHOE @ 828' FROM 878-778'. (IF 7" CSG NOT RECOVERED. PERFORATE AND SQUEEZE 50 SX CLASS C NEAT CMT PLUG). **PLUG MUST BE TAGGED!**
- PUH TO 30'. SPOT 15 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
- ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock TITLE Regulatory Technician DATE 08-03-93
 TYPE OR PRINT NAME Kaye Pollock TELEPHONE NO. 915-888-2584

(This space for State Use)

APPROVED BY Orig. Signed by Paul Kautz Geologist TITLE Geologist DATE AUG 05 1993
 CONDITIONS OF APPROVAL, IF ANY:

STATE G # 2
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO


RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. RIH W/ WS TO 2861'. LOAD HOLE W/ 10 PPG GELLED BRINE. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS SALT BASE @ 2811' AND TOC @ 2670' FROM 2861-2620'.
3. PUH TO 1853'. CUT AND PULL 7" CSG OR PERFORATE AND SQUEEZE 50 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @ 1803' FROM 1853-1753'. **PLUG MUST BE TAGGED!**
4. PUH TO 878'. SPOT 50 SX CLASS C NEAT CMT PLUG ACROSS 10-3/4" CSG SHOE @ 828' FROM 878-778'. (IF 7" CSG NOT RECOVERED, PERFORATE AND SQUEEZE 50 SX CLASS C NEAT CMT PLUG). **PLUG MUST BE TAGGED!**
5. PUH TO 30'. SPOT 15 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
6. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

STATE G
WELL # 2
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO
CURRENT COMPLETION

KB = 4012'
GL = 4001'

H, 24, T 17-S, R 34-E, 1980' FNL, 660' FEL



STATE G
WELL # 2
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO
PROPOSED COMPLETION

H, 24, T 17-S, R 34-E, 1980' FNL, 660' FEL

KB = 4012'

GL = 4001'

15 SX CLASS C NEAT CMT PLUG
FROM SURFACE-30'

10-3/4" 40# L.W. CSG CMT'D
W / 231 SX CIRC. @ 828'

50 SX CLASS C NEAT CMT PLUG ACROSS CSG SHOE @
828' FROM 878-778'
PLUG MUST BE TAGGED!

50 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @
1803' AND 7" CSG STUB FROM 1853-1753'
PLUG MUST BE TAGGED!

TOC @ 2670' (CALCULATED)

50 SX CLASS C NEAT CMT PLUG ACROSS SALT BASE @
2811' AND TOC @ 2670' FROM 2861-2620'

PBTD=4235'

BELL CIBP @ 4270' W/ 35' CMT CAP

7" 24# SL CSG CMT'D
W / 231 SX @ 4350'

SAN ANDRES OH FROM 4350-4750'

TD=4750'

STATEG2P.PRE
ALS 08/02/93