NO. OF COPIES RECEIVED		•	"
DISTRIBUTION	1		Form C-103
			Supersedes Old C-102 and C-103
SANTAFE	-	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			
			5. State Oil & Gas Lease No.

(20 NOT HER THIS	SUNDRY NO	ICES AND REPORTS ON WELLS	
US NOT USE THIS	*APPLICATION FO	ICES AND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.			7. Unit Agreement Name
OIL X GA		ER•	
2. Name of Operator			
	211 0		8. Farm or Lease Name
Socony Mobil	J11 Company	Inc.	State Bridges State
3. Address of Operator			9. Well No.
Box 1800, Hol	os. New Mex	co	11
4. Location of Well			
-	÷000	N 11 12 22 22 22	10. Field and Pool, or Wildcat
UNIT LETTER		FEET FROM THE North LINE AND 1978.5 FEET FROM	Vacuum Blinebry
THE West	JAE, SECTION	25 TOWNSHIP 17 S RANGE 34 E NMPM	
		RANGE NMPM	
	17777777	15. Elevation (Show whether DF, RT, GR, etc.)	<u>annuniiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii</u>
	///////////////////////////////////////	4013 GR	12. County
	777777777	3	Lea
10.	Check Appro	riate Box To Indicate Nature of Notice, Report or Ot	her Data
NOT	SE OF INTEN		
		SUBSEQUEN	T REPORT OF:
Г	ן		
PERFORM REMEDIAL WORK	١	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORABILY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS CASING TEST AND CEMENT JOB	TOO AND ABANDONMENT
_	-		
		OTHER	
OTHER		[] [
OTHER			
			estimated date of starting any proposed
17. Describe Proposed or C : work) SEE RULE 1103.	mpleted Operation 6800 T.	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-6563	estimated date of starting any proposed
17. Describe Proposed or C. work) SEE RULE 1103.	mpleted Cheretion 6800 T.	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-0563. Well Service Unit. Pull rods & pump. Pul	l tubing. Ran nacker
17. Describe Proposed or C work) SEE RULE 1103. Move in & rigg on 2" tubing a	mpleted Countion 6800° T. d up Loman: 6348° S	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563.	l tubing. Ran packer
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha	mpleted Control of 800° T. d up Loman: 6348°. S. e L-26 + 5	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563. w/20# 20-40 sand. Breakdown @ 4500#. TP 600	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S	mpleted Counting 6800 T. dup Loman: 6348 S. s. e L-26 + 5	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab & BLO in 28 hours. Pull 2" tubing	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420*, clea	mpleted Counties 6800 T. d up Loman: 6348'. S. e L-26 + 5 18 hours. out frac	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-0563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563 w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770. Pull tubing. prepare to put	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420*, clea	mpleted Counties 6800 T. d up Loman: 6348'. S. e L-26 + 5 18 hours. out frac	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-0563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563 w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770. Pull tubing. prepare to put	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning	mpleted Control of 800° T. d up Loman: 6348° S.e L-26 + 5 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563. W/20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770. Pull tubing. prepare to put tubing to 6728. tubing perfs. 6536-39.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535! Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770 PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563. W/20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770. Pull tubing. prepare to put tubing to 6728. tubing perfs. 6536-39.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 1850.	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Control of 800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1703. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO	mpleted Controller 6800° T. d up Loman: 6348°. S.e L-26 + 5. 18 hours. out fracout. Ran:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab & BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + & BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Wiell Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab & BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + & BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran NMOCC potential test- 600 Production before
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab & BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + & BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran NMOCC potential test- 600 Production before
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran NMOCC potential test- 600 Production before
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Coloration 6800° T. d up Loman : 6348°. S e L-26 + 5 18 hours. out frac out. Ran : 6335°. Pur & BSW in :	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran NMOCC potential test- 600. Production before
17. Describe Proposed or C. work) SEE RULE 1103. Move in & rigg on 2" tubing a + 600# Phospha ISIP 3000#. S to 6420', clea while cleaning rods & pump to pumped 10 BNO workover - 0.	mpleted Countries 6800° T. d up Loman 6348° S e L-26 + 5 18 hours out frac out. Ran: 6335° Pui 8 BSW in:	(Clearly state all pertinent details, and give pertinent dates, including 6770' PBTD Blinebry Perfs. 6412-6563'. Well Service Unit. Pull rods & pump. Pul nd-oil frac. Blinebry perfs. 6412-6563' w/0# 20-40 sand. Breakdown @ 4500#. TP 600 Swab 88 BLO in 28 hours. Pull 2" tubing and to 6770'. Pull tubing. prepare to put tubing to 6728', tubing perfs. 6536-39'. p 327 BLO+48BSW + 8 BNO in 184 hours. On 14 hours, 15-64 SPM. GOR 1550, Gty. 36.1 @	l tubing. Ran packer 2000 gals. refined oil 0-5900#. Rate 4.7 BPM & packer. Ran tubing on pump. Lost 30 BLO SN at 6535'. Ran NMOCC potential test- 600 Production before