

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02106
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name VACUUM GLORIETA WEST UNIT / was Bridges State
8. Well No. 12 / was 36
9. Pool name or Wildcat VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC. / Was Mobil Producing TX & NM Inc.
3. Address of Operator P.O. BOX 3109, MIDLAND, TX 79702	4. Well Location Unit Letter D : 660 Feet From The NORTH Line and 660 Feet From The WEST Line Section 26 Township 17-6 Range 34-E NMMP LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL-4023	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU; DIG PIT; FLOW WELL TO PIT. ND WH. NU BOP.
TAG CMT @ 4953. LOAD HOLE W/BRINE. PUMP 45 SX CL C FROM 4953-4400.
POOH TO 4291. MIX & PUMP 30 SX CL C FROM 4291-4017.
POOH TO 2400. RIH W/SHOT ON WL & PERF 7" CSG @ 2608. POOH W/WL.
PU PKR & RIH TO 2400. SET PKR & EST INJ RATE. MIX & SQZ 50 SX CL CL PLUG FROM 2608-2508.
RIH W/WL TO 1750 & PERF. POOH W/WL.
RIH W/PKR TO 1600. SET & EST INJ RATE. MIX & SQZ 50 SX CL C FROM 1750-1650.
POOH W/TBG & PKR. RUN 7" CSG. RIH W/WL & CUT 7" CSG @ +/-850. POOH W/WL & CSG.
RIH W/WS TO +/-800. SPOT 70 SX CL C PLUG FROM 900-765. TAG.
POOH W/TBG LD. ND BOP. RIH W/1 JT TBG TO 30. SPOT 15 SX CL C FROM 30 TO SURFACE. POOH W/WS.
ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3 FT BELOW SURFACE. WELD STEEL PLATE ON CSG STUB.
ERECT P & A MARKER WITH WELL NAME & PLUGGED DATE. FILL CELLAR & CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock-Lyon TITLE ENV. & REG. TECHNICIAN DATE 09-08-94

TYPE OR PRINT NAME KAYE POLLOCK-LYON AS AGENT FOR TEXACO

TELEPHONE NO. 915-688-2584

(This space for State Use)

APPROVED BY Larry W. Wink TITLE FIELD DATE SEP 09 1994

CONDITIONS OF APPROVAL, IF ANY:

BRIDGES STATE # 36
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO

RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. RIH W/ 2-3/8" TBG & TAG CMT @ $\pm 4953'$. LOAD HOLE W/ 10 PPG GELLED BRINE. MIX & PUMP 45 SX CLASS C NEAT CMT PLUG FROM 4953-4400' ACROSS SAN ANDRES PERFS @ 4743-4811' & 4448-4526'.
3. POOH W/ TBG LD UP TO 4291'. MIX & PUMP 30 SX CLASS C NEAT CMT PLUG FROM 4291-4017' ACROSS 7" CSG SHOE @ 4241' & 5" LINER TOP @ 4067'.
4. POOH W/ TBG LD UP TO 2400'. POOH W/ REMAINING TBG STANDING BACK IN DERRICK. RU WIRELINE. RIH W/ SHOT ON WL & PERF 7" CSG @ 2608'. POOH W/ WL.
5. PU 7" PKR & RIH ON TBG TO 2400'. SET PKR & ESTABLISH INJ RATE. MIX & SQZ 50 SX CLASS C NEAT CMT PLUG FROM 2608-2508' ACROSS SALT BASE @ 2558'. DISPLACE CMT TOP TO 2508'. POOH W/ TBG LD UP TO 1500'. POOH W/ REMAINING TBG STANDING BACK IN DERRICK.
6. RIH W/ WL TO 1750' & PERF 7" CSG. POOH W/ WL.
7. RBIH W/ 7" PKR ON TBG TO 1500'. SET PKR & ESTABLISH INJ RATE. MIX & SQZ 50 SX CLASS C NEAT CMT PLUG FROM 1750-1650' ACROSS SALT TOP @ 1700'. DISPLACE CMT TOP TO 1650'.
8. POOH W/ TBG & PKR. RUN FREEPOINT ON 7" CSG. RIH W/ WL & CUT 7" CSG @ $\pm 850'$. POOH W/ WL. POOH & LD 7" CSG.
9. RIH W/ WS TO $\pm 900'$. SPOT 70 SX CLASS C NEAT CMT STUB PLUG FROM ± 900 -765' ACROSS 7" CSG STUB @ $\pm 850'$ & 10-3/4" CSG SHOE @ 815'. **PLUG MUST BE TAGGED!**
10. POOH W/ TBG LD. ND BOP. RBIH W/ 1 JT TBG TO 30'. SPOT 15 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
11. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

BRIDGES STATE
WELL # 36
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO
CURRENT COMPLETION

D, 25, T 17-S, R 34-E, 660' FNL, 660' FWL

GL = 4023'

10-3/4" 35.75# LW CSG @ 815'
CMT'D W / 257 SX CIRC.


TOC @ 2705' (CALC)

TOL @ 4067'

7" 24# SL CSG @ 4241'
CMT'D W / 217 SX CIRC.

CSG LEAKS SQZ'D W/ 67 SX
FROM 4241-4991'
CMT DRL'D OUT TO 4953'

5" 15# N-80 LINER 4067-6900'
CMT'D W / 425 SX CIRC.



SAN ANDRES PERFS
4448-4526' SQZ'D W/ 75 SX CMT

SAN ANDRES PERFS
4743-4811' SQZ'D W/ 100 SX CMT

CMT FROM 4953-4991'
5" CIBP @ 5010'
5" CIBP @ 6350' W/ 20' CMT CAP

BLINEBRY PERFS
6419-6705'
5" BAKER MODEL "D" PKR @ 6828'

PBTD=4953'
TD=6900'

