

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-155
7. Lease Name or Unit Agreement Name Central Vacuum Unit
8. Well No. 91
9. Pool name or Wildcat Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Texaco Exploration and Producing Inc.	
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3991' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1). Notify NMOCB before plugging. Work will commence upon approval.

2). MIRU pulling unit. Install BOP. Pull 2 3/8" tbg and pkr.

3). TIH w/workstring to PBTD (3787'). Tag plug at 3787'. Load hole w/salt gel mud consisting of 10 ppg brine w/25 lbs gel per bbl.

4). Spot 10 sx plug of class "C" cmt from 2700'-2800'.

5). Csg leak at 1872'-1900'. Establish rate and pressure thru csg leak. TOH w/tbg.

6). By wireline, set cmt retainer at 1800'. TIH w/workstring and sting into cmt retainer. Squeeze csg leak w/15 sx class "C" cmt. Sting out of retainer. Circulate cmt to surface.

7). Spot 10 sx class "C" cmt from 1450'-1550'.

7). Spot 50' plug (5 sx class "C" cmt) at surface.

8). Cut off wellhead. Install dry hole marker.

9). Rig down pulling unit. Clean location.

SIGNATURE Richard DeSoto TITLE Engineering Technician DATE 07-24-91

TYPE OR PRINT NAME R. B. DeSoto

TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY JERRY SEXTON TITLE OIL & GAS INSPECTOR DATE 07 30 1991

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 29 1961

GOV
MOBILE CHAMBER