STATE OF NEW MEXICO		
IERGY AND MINERALS DEPARTMENT	•	
OIL CONSERVATION DIVISION		
DISTRIBUTION P. O. BOX 2088	Forg C-103	
F. O. BOX 2088	Revised 10-1-	
SANTA FE SANTA FE, NEW MEXICO 87501		
U.S.C.S.	Sa. Indicate Type of Lease	
LAND OFFICE	State X Fee	
OPERATOR	5. State Oil & Gas Lease Ho.	
	V-1520	
SUNDRY NOTICES AND REPORTS ON WELLS	annin minnin	
DUNDATING THE DATA STOPHILE DATA TO DELLA TO DE TO DE TA DE TODELLA DE TELLA 100 HOT USE THIS FORM FOR PORDALS TO DELLA DE TO DECEMIN DE PLUS BALA TO A DEFRECEENT RESERVOIR. USE "APPLICATION FOR PENNIT "FORM CHOIT FOR SUCH PERDODALS.]	$\sim \lambda (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)$	
	7. Unit Agreement Lizze	
	, one horeenten richte	
	8. Form or Lease trame	
T. H. McElvain Oil & Gas Properties	New Mexico AC State	
tress of Operator	9. Well No.	
P.O. Box 2148, Santa Fe, NM 87504-2148	#1	
stion of mell	10. Fleid and Pool, or Wilarat	
H 1980 FLET FROM THE NOTTH LINE AND 660 FLET F	South Chao Bon Atala	
NIT LETTER I FEET PROM THE LINE AND OUU FEET PROM THE LINE AND	South Shoe Bar Atoka	
Fact 22 170 ora		
HE EAST LINE, SECTION 22 TOWNSHIP 175 RANCE 35E NO	···· []]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3926 GL	Lea	
Check Appropriate Box To Indicate Nature of Notice, Report or	Other Data	
•	ENT REPORT OF:	
	INT REPORT OF:	
CAM BEWEDIAL WORK	ALTERING CASING	
DAARILT ABANDON	PLUG AND ABANDONMENT	
DA ALTER CASING L CHANGE PLANS L CASING TEST AND CEMENT 103 X	_	
other squeez	ie 🗌	
nca		

7. Describe Proposed or Completes Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled out cement plugs and cut out junk to 11955. Tested casing. Would not hold pressure. Isolated leaks between 6116 to 6409 and 9490 to 9940. Set cement retainer at 9490 and squeezed with 50 sks. at 1.5 to 2 BPM increasing steadily to 0.1 BPM at 5500 psi. Shut down and pressure held steady at 5200 for 30 minutes. Strung out of retainer and circ. 15 sks. to pit. Used 25 sks. Class H with 0.6% CF-14 + 25 sks. Class H Neat. Went in hole open ended and spotted cement from 6569 to 5420. Pull tubing to 5000 free. Squeezed 50 sks. at 800 psi. Tagged cement at 6430. Spotted 50 sks. from 5400 to 6430. Pull up tubing and squeeze at 900 psi. Tag cement at 6215. Spot 75 sks. in stages from 6215 to 5375. Maximum squeeze pressure 4250 psi. Left pressure overnight. Used 100 sks. of Class H with 0.6% CF-14 and 75 sks. Class H Neat. WOC 18 hrs. Drilled out cement and tested casing from surface to 11955. Squeeze broke at 4650 psi. Found pressure leak in interval from 6116 to 6409. Went in hole with packer to 5865. Squeezed in 5 stages with 200 sks. Class H Neat cement. Final squeeze pressure 5000 psi. Reversed out 15 bbls. cement and left well shut in with 5000 psi on squeeze. Finished squeeze at 1800 on 12-13-85. WOC 18 hrs. Drilled out cement and pressure tested casing to 5000 psi from surface to 11955 for 30 minutes. Held ok.

18. I hereby dertaly that the information prove to true and complet	te to the	best of my knowledge and belief.		
man Ange & Droomf			DATE_	12-24-85
ORIGINAL SIGNED BY JERRY SEXTOR DISTRICT I SUPERVISOR	• · · · · · · · · · · · · · · · · · · ·	•		DEC 2 7 1985



- .

.