


TEXACO E&P INC.
CENTRAL VACUUM UNIT No. 64
API# 30025029530000



PBTD @ 4600'

115 gallons Quacore 1200 Resin
TD 2 SX raised on top of casing plug

1980 FNL & 1980 FNL
SEC 31, T1N 17 S, RANGE 35 E
ELEVATION: 3991 ES
COMPLETION DATE: 02-26-38

COMPLETION INTERVAL: 4100 - 4710 (CBSA)
Former Marathon Worn Slate A/C-2 No. 1

CVU 64 Procedure

Note: Begin workover on the 1st of the month. Schedule soak period for production to begin the following month. There should not be injection and production by the same well in the same month.

1. Begin installation of temporary CO2 injection line from Satellite #4 injection header to CVU 64. Install temporary line from header position of CVU 45 with line heading north and looping back to the south around the header. This line will be used for CVU 63 immediately following injection into CVU 64. CVU 45 will be shut in during the injection to CVU 64. Perform all necessary Lock Out and Tag Out at Header and Well. CVU 45's injection metering will be used to control the injection rate and pressure.
2. Pressure test line to 2500 psi using fresh water.
3. MIRU pulling unit and POOH with production equipment laying down.
4. PU workstring. TIH with 6 1/8" bit and casing scraper and clean out to casing shoe at 4100'. Clean out to PBTD and tag up resin plug at about 4600'. Note any carbonate or sulfate scale in returns. TOH with tools laying down tubing.
5. TIH with packer and injection tubing. Set packer at 4000'. Install tree. Pressure test annulus to 500 psi. Leave 200 psi on annulus and shut in. RDMO.
6. Connect well to temporary injection line. Set injection pressure at 1000 psi. Open valve at header and begin CO2 injection.
7. CO2 injection will be monitored. After 50MMSCF of CO2 injection (approximately 2 weeks), water will be injected for 1 hour to purge the flowline and displace some of the tubing. The well will be shut in to soak for 1 week.
8. During the soak, remove the temporary line and connect the production flowline to the well adding a choke at the wellhead to control the flowline pressure. Re-connect CVU 45 and return to H2O injection.
9. Begin flowing back well and testing.
10. When the well is nearly dead, the packer and tubing will be pulled and the production tubing and pump will be rerun in the well. (The injection tubing and packer will be stored in the warehouse, for use in CVU 63.)
11. Return well to production.