## STATE OF NEW MEXICO **ENERGY AND MINERALS DEPARTMENT**

## **OIL CONSERVATION DIVISION**

87501	Form C-103
	Revised 10-1-78

NO. OF COPIES RECEIVED		P O.BOX					
DISTRIBUTION	SANTA FE	E, NEW N	IEXICO 87501			Form C-	
SANTA FE						Revised	10-1-78
FILE				[5. \ t \			
U.S.G.S				5a. Indicate	_		_
LAND OFFICE				State	×	Fee	<u> </u>
API No. 30-025-02979				5. State Oil & Gas Lease No B-1838-1			
SU	NDRY NOTICES AND REPORT	S ON WE	115	777777	<u> </u>	$\overline{m}$	m
(DO NOT USE THIS FORM USE "	FOR PROPOSALS TO DRILL OR TO DEEPEN OR F APPLICATION FOR PERMIT - * (FORM C-101) FOR	PLUG BACK TO	A DIFFERENT RESERVOIR,				
l. Oil ga	s			7. Unit Agre			
WELL X WE				East V	acuur	m Gb/SA	Unit
<ol> <li>Name of Operator Phillips Petroleul</li> </ol>	m Company			8 Farm or Le		me 11 Gb/SA	Unit
3. Address of Operator			title - attitude on attitude on an an attitude attitude on a second	9 Well No.			
4001 Penbrook Street, Odessa, Texas 79762				004			
14. Location of Well			10. Field and Pool, or Wildcat				
UNIT LETTER F . 1980 FEET FROM THE West LINE AND 1980 FEET FROM			Vacuum Gb/SA				
	on 32 Township			//////			
mmmm	15. Elevation (Show wheth	h 05 07	CD ata\	777777	7777	<del>/////</del>	444
	3974 GR	ner Dr, Ki,	Gr, etc.)	12. County	-		
Short Charles	77777	<del></del>		Lea		77777	77777
<sup>o.</sup> Check	Appropriate Box To Indicate	Nature o	f Notice, Report or Ot	her Data			
NOTICE OF INT	ENTION TO:	1	SUBSEQU	JENT REPOR	T OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	п	REMEDIAL WORK	٦			_
TEMPORARILY ABANDON	VEGG NIID REALIDON	<b>-</b>	COMMENCE DRILLING OPNS.		ALTERI	ING CASING	
PULL OR ALTER CASING	CHANGE PLANS			<del></del>	PLUG A	AND ABANDONI	MENT
		_	CASING TEST AND CEMENT JOB	J			
отиек Deepen, log, r	un liner, perf	X	OTHER				🗆
commended procedure t	Operations (Clearly state all pertinate of Operations of Clearly state all pertinate of Operations (Clearly state all pertinate of Operations of Clearly state all pertinate of Operations (Clearly state all pertinate of Operations of Clearly state all pertinate of Operations (Clearly state all pertinate of Operations of Ope	' from					
J DDU. ND wellhead. Ss on 2-7/8" workstrir It to 4800'. Circulat	San Andres and stimula NU BOBs. TOOH w/ tbg. ng. TIH to 4620'. Disce & condition hole for from 4800' to 4178' from 4800' to 4178'	. & pmp splace	hole with pre-mix	ked fresh	water	r mud.	Drill
(H, circulate and conducess.	lition hole to run 5" 1	liner.	Cement liner usi	ing calipe	er vo	lume plu	ıs 30%
		cellop	nane, 0.4% CF-2.		'ns	<b></b>	- د د.
8. I hereby certify that the information about	W. J. Mueller	•	ring Supervisor, Resv.		DATE	everse s	/88
PPROVED BY ORIGINAL SIGNED	BY JERRY SEXTON TITLE					IAN -	<b>#</b>

Set packer. Circulate cement from top of liner. TOOH. WOC. GIH to check pBTD and spot 10 bbls acetic acid from 4750' to  $\pm 4200$ '. Pressure test liner and BOP to 2000 psi prior to perforating. Run correlation log and perforate. Install lubricator and test to 3000 psi. Perforate the 5" liner from top to bottom with 3-3/8" 0.0. centralized casing guns with premium DML charges at 2 bottom with 3-3/8" 0.0. centralized casing guns with premium DML charges at 2 bottom with 3-3/8" 0.0. centralized casing guns with premium pmL charges at 2 packer at 4200'. Swab test to clean up all perforations. Rerun production

.inemqiupe

JAN 7 1988
OCD
HOBBS OFFICE