

ATTACHMENT I

Item 12 (continued)
P&A Procedure

8. Set CIBP at 9500' and bail 35' cement onto plug.
9. Set CIBP at 7000' and bail 35' cement onto plug.
10. RIH with open ended tubing. Spot 100' cement plug from 408'-3980'.
11. POOH w/tbg.
12. Perf (4) holes @ 1890'.
13. RIH w/tbg. Spot 150' cement plug inside and outside 7" csg. Reverse circulate hole with 10 ppg brine.
14. POOH with tbg. WOC.
15. RIH with tbg & tag cement. POOH.
16. ND BOP's.
17. Spot cement plug from 50' to surface.
18. Cut off casing, weld on plate, install marker.
19. RD pulling unit.
20. Clean location and battery site.

Note: Procedure discussed with Mr. Paul Kautz of N.M.O.C.D on October 5, 1988.