District Office		d Natural Resources Department	Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM	Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-03173
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, I			5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
( DO NOT USE THIS F DIFF	NDRY NOTICES AND REPOR ORM FOR PROPOSALS TO DRILL OI ERENT RESERVOIR. USE "APPLICA (FORM C-101) FOR SUCH PRO	R TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT"	
I. Type of Well: OIL WELL	OAS WELL OT	HER TA-Oil Well	East Pearl Queen Unit
2. Name of Operator Pyramid Ener	rav. Inc.		8. Well No. 10
1 I dd a of Operator		The my 70216	9. Pool name or Wildcat
10101 Reunio	on Place, Ste. 210 San	Antonio, TX 78210	Pearl Queen
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN	Check Appropriate Box ICE OF INTENTION TO: WORK PLUG AND ABA NG CHANGE PLAN	ANDON REMEDIAL WORK	JBSEQUENT REPORT OF:
05/16/94	Set CIBP at 4490' abo	ve existing cement plug	& tested casing. Casing leaked.
	Tagged CIBP at 4490'		
06/01/94	1600' to 950'. Obtai sacks cement at 1700' overnight. Tagged t Pumped 70 sacks of ce to surface between th 5 1/2" casing from su	ted holes in casing with ned plugging instruction and squeezed leaks to op of cement at 903'. ment down 5 1/2" casing e 5 1/2" and 8 5/8" cas	th mud. Spotted 25 sacks of th tubing and packer from ons from NMOCD. Spotted 100 500 psi. Wait on cement Perforated casing at 140'. g and circulated cement back sing. Left cement inside the f wellhead 3' below ground lugged and abandoned.
	1600' to 950'. Obtai sacks cement at 1700' overnight. Tagged t Pumped 70 sacks of ce to surface between th 5 1/2" casing from su level and welded on c	ted holes in casing with ned plugging instruction and squeezed leaks to op of cement at 903'. ment down 5 1/2" casing the 5 1/2" and 8 5/8" casing trace to 140'. Cut of ap and marker. Well p	th tubing and packer from ons from NMOCD. Spotted 100 500 psi. Wait on cement Perforated casing at 140'. g and circulated cement back sing. Left cement inside the f wellhead 3' below ground
I hereby certify that the in	1600' to 950'. Obtai sacks cement at 1700' overnight. Tagged t Pumped 70 sacks of ce to surface between th 5 1/2" casing from su level and welded on c	ted holes in casing with ned plugging instruction and squeezed leaks to op of cement at 903'. ment down 5 1/2" casing at 5 1/2" and 8 5/8" cas afface to 140'. Cut of ap and marker. Well p	th tubing and packer from ons from NMOCD. Spotted 100 500 psi. Wait on cement Perforated casing at 140'. g and circulated cement back sing. Left cement inside the f wellhead 3' below ground
	1600' to 950'. Obtai sacks cement at 1700' overnight. Tagged t Pumped 70 sacks of ce to surface between th 5 1/2" casing from su level and welded on c	ted holes in casing with ned plugging instruction and squeezed leaks to op of cement at 903'. ment down 5 1/2" casing the 5 1/2" and 8 5/8" casing of my knowledge and bedief.	th tubing and packer from ons from NMOCD. Spotted 100 500 psi. Wait on cement Perforated casing at 140'. g and circulated cement back sing. Left cement inside the f wellhead 3' below ground lugged and abandoned.

. . Ú

## RECEIPTO

----

ten acort

• •

,