

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
B-1553

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State E Tract 18
3. Address of Operator P. O. Box 68 Hobbs, New Mexico 88240	9. Well No. 18
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17-S</u> RANGE <u>36-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Lovington Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3848' RDB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the subject well per the following:
Move in service unit and RIH with 2 3/8" tubing. Tag tubing anchor stuck at 6093'. Spot 50 sx of Class C neat above anchor. Spot 35 BBLs 10# brine with 25# gel per BBL. Spot 25 sx of Class C neat at ±4975'. Spot 65 BBLs 10# brine with 25# gel per BBL. Perforate 7" casing at 3280'-3281' with 4JSPF. RIH with a cement retainer and set at 1950'. Establish circulation through 7"-9 5/8" annulus. Pump 650 sx Class C neat. Circulate cement through 7"-9 5/8" casing annulus. Spot 66 BBLs 10# brine with 25# gel per BBL. Perforate through the 7" and 9 5/8" casing strings at 275'-276' with 4JSPF. Pump down the 7" casing to establish circulation through the 9 5/8"-13 3/8" annulus. Pump down the 7" casing 85 sx Class C neat and circulate through the 9 5/8"-13 3/8" annulus. Leave casing full to surface with cement. Weld on cap and erect permanent abandonment marker.

* Notify NMOCD prior to setting plugs.

0+4-NMOCD,H 1-HOU, R.E. Ogden RM 21.150 1-F.J. Nash, HOU Rm. 4.206 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Sexton TITLE Admin. Analyst DATE 6-24-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: