Office District I	State of Energy, Minerals	t New Me s and Nati			Form U Revised March 25	
1625 N. French Dr., Hobbs, NM 88240	BJ, minoral	- unu riuli		ELL API NO		, 1777
Distr'ct II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSER	VATION	JDIVISION	30-025-03883		
District III 1220 South St. Francis Dr.				5. Indicate Typ	e of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410				STATE	FEE 🗆	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa P	Fe, NM 8	/505	6. State Oil &	Gas Lease No.	
87505				B-3009		
SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well:	CES AND REPORTS O SALS TO DRILL OR TO DEI CATION FOR PERMIT" (FOI	EDEN OD DI	UC DACK TO A	7. Lease Name	or Unit Agreement N	lame:
Oil Well 🔲 Gas Well 🗍 Other Water Injection Well				West Lovington Unit		
2. Name of Operator				8. Well No.		
Pure Resource				32		
3. Address of Operator 500 West Illinois Midland Terrer 70701				9. Pool name or Wildcat		
500 West Illinois – Midland, Texas 79701 4. Well Location				Lovington San Andres West		
			:0		$F_{4} < 2$	
Unit LetterO_:660	feet from theSC	)UTH	line and <b>660</b>		e	e
Section 5	Township	17S	Range 36E	NMPM	Lea County	
	10. Elevation (Show	whether Di	R, RKB, RT, GR, etc	)	County	
11. Check	Appropriate Box to	Indicate	Noturo of Notice	Denset Ott	<b>D</b>	
NOTICE OF IN		mulcale		, Report or Oth	er Data	
NOTICE OF INTENTION TO:         SUE           PERFORM REMEDIAL WORK         PLUG AND ABANDON         REMEDIAL WOR				SEQUENTRE		
_					ALTERING CASIN	GЦ
	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN		ABANDONMENT	
	COMPLETION		CEMENT JOB			
OTHER:			OTUER			
. Describe proposed or completed	operations (Clearly at		OTHER:			•
of starting any proposed work).	SEE RULE 1103. For N	Aultiple Co	ompletions: Attach v	e pertinent dates, wellbore diagram	including estimated c of proposed completi	late on or
13 3/8" 48# Set at 330'						'
15 5/0 40# Set at 530						
8 5/8" 28# casing set at 2,000'						
8 5/8" 28# casing set at 2,000' 5 1/2" 14# casing set at 4,675' Open Hole completion 4,675'-5,0	)80'					
8 5/8" 28# casing set at 2,000'	)80' er LOK-SET)					
8 5/8" 28# casing set at 2,000' 5 <sup>1</sup> /2" 14# casing set at 4,675' Open Hole completion 4,675'-5,0 <b>Injection packer at 4,565' (Bak</b>	er LOK-SET)					
8 5/8" 28# casing set at 2,000' 5 1/2" 14# casing set at 4,675' Open Hole completion 4,675'-5,0 Injection packer at 4,565' (Bak Failed Mechanical Integrity Te:	er LOK-SET) st: Excessive Pressure	Loss.				·
8 5/8" 28# casing set at 2,000' 5 <sup>1</sup> ⁄ <sub>2</sub> " 14# casing set at 4,675' Open Hole completion 4,675'-5,( Injection packer at 4,565' (Bak Failed Mechanical Integrity Te Corrective Action Completed: 11	er LOK-SET) st: Excessive Pressure 1-08-02				· · ·	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bak</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottom</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611?	' Could n	ot achieve a good tes	st from 611' to sur	face. Performed a ca	asing
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Baker Failed Mechanical Integrity Text)</li> <li>Corrective Action Completed: 11 Set RBP at 4,520'. Isolated botto back-off at 673'. Replaced ton 6'</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 14'' 14# casing u	'. Could no				
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,(</li> <li>Injection packer at 4,565' (Bak</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated botto</li> <li>back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack	'. Could no with new 5 ker and tub			casing and ran an in acker fluid. Ran pre	
8 5/8" 28# casing set at 2,000' 5 ½" 14# casing set at 4,675' Open Hole completion 4,675'-5,0 Injection packer at 4,565' (Bak Failed Mechanical Integrity Te Corrective Action Completed: 11 Set RBP at 4,520'. Isolated botto back-off at 673'. Replaced top 6' pressure test. Retrieved RBP and chart and looked good. Rigged de	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack own and released pulling	'. Could no with new 5 ker and tub g unit	$\frac{12^{-1}}{15.5\#}$ casing. So ping to FHD of 4,565		casing and ran an in backer fluid. Ran pre	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Baker Failed Mechanical Integrity Text)</li> <li>Corrective Action Completed: 11 Set RBP at 4,520'. Isolated botto back-off at 673'. Replaced top 6' pressure test. Retrieved RBP and chart and looked good. Rigged de Post workover mechanical integrity</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack own and released pulling	'. Could no with new 5 ker and tub g unit	$\frac{12^{-1}}{15.5\#}$ casing. So ping to FHD of 4,565		casing and ran an in acker fluid. Ran pre	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bake</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottot back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged de</li> <li>Post workover mechanical integrity Starting Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack own and released pulling	'. Could no with new 5 ker and tub g unit	$\frac{12^{-1}}{15.5\#}$ casing. So ping to FHD of 4,565		casing and ran an in backer fluid. Ran pre ريان	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Baker Failed Mechanical Integrity Text)</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated botton back-off at 673'. Replaced top 6' pressure test. Retrieved RBP and chart and looked good. Rigged de Post workover mechanical integrity</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack own and released pulling	'. Could no with new 5 ker and tub g unit	$\frac{12^{-1}}{15.5\#}$ casing. So ping to FHD of 4,565	crewed back on to 5.19'. Circulated r	casing and ran an in acker fluid. Ran pre	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bake</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottot back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged de</li> <li>Post workover mechanical integrity Starting Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1/2" 14# casing v I RIH with injection pack own and released pulling	'. Could no with new 5 ker and tub g unit	$\frac{12^{-1}}{15.5\#}$ casing. So ping to FHD of 4,565		casing and ran an in acker fluid. Ran pre	
8 5/8" 28# casing set at 2,000' 5 1/2" 14# casing set at 4,675' Open Hole completion 4,675'-5,( Injection packer at 4,565' (Bak Failed Mechanical Integrity Ter Corrective Action Completed: 11 Set RBP at 4,520'. Isolated botto back-off at 673'. Replaced top 6' pressure test. Retrieved RBP and chart and looked good. Rigged d Post workover mechanical integ Starting Pressure: 360 PSI Final Pressure: 360 PSI	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 1⁄2" 14# casing v I RIH with injection pack own and released pulling grity test was witnessed	'. Could no with new 5 ker and tub g unit I by Bill Pr	<sup>1/2</sup> 15.5# casing. So ping to FHD of 4,565 ritchard 11-8-02.	crewed back on to 5.19'. Circulated p	casing and ran an in acker fluid. Ran pre	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,(</li> <li>Injection packer at 4,565' (Bak</li> <li>Failed Mechanical Integrity Te:</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated botto</li> <li>back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and</li> <li>chart and looked good. Rigged d</li> <li>Post workover mechanical integ</li> <li>Starting Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 ½" 14# casing v I RIH with injection pack own and released pulling grity test was witnessed	2. Could no with new 5 ker and tub g unit a by Bill Pr by Bill Pr te to the bes	viritchard 11-8-02.	crewed back on to 5.19'. Circulated p	casing and ran an in acker fluid. Ran pre	
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,(</li> <li>Injection packer at 4,565' (Bak</li> <li>Failed Mechanical Integrity Te:</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated botto back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged d</li> <li>Post workover mechanical integ</li> <li>Starting Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 ½" 14# casing v I RIH with injection pack own and released pulling grity test was witnessed	2. Could no with new 5 ker and tub g unit a by Bill Pr by Bill Pr te to the bes	<sup>1/2</sup> 15.5# casing. So ping to FHD of 4,565 ritchard 11-8-02.	and belief.	DATE: December	itial essure 3, 200
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bake</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottot back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged de</li> <li>Post workover mechanical integrity Tex</li> <li>Starting Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 ½" 14# casing v I RIH with injection pack own and released pulling grity test was witnessed	2. Could no with new 5 ker and tub g unit a by Bill Pr by Bill Pr te to the bes	viritchard 11-8-02.	and belief.	casing and ran an in acker fluid. Ran pre	itial essure 3, 2002
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bake</li> <li>Failed Mechanical Integrity Text</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottot back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged de</li> <li>Post workover mechanical integrity Text</li> <li>Starting Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> <li>Final Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 om of casing leak at 611' 73' of 5 ½" 14# casing v I RIH with injection pack own and released pulling grity test was witnessed	2. Could no with new 5 ker and tub g unit a by Bill Pr by Bill Pr te to the bes	viritchard 11-8-02.	and belief.	DATE: December	itial essure 3, 2002
<ul> <li>8 5/8" 28# casing set at 2,000'</li> <li>5 ½" 14# casing set at 4,675'</li> <li>Open Hole completion 4,675'-5,0</li> <li>Injection packer at 4,565' (Bake</li> <li>Failed Mechanical Integrity Tex</li> <li>Corrective Action Completed: 11</li> <li>Set RBP at 4,520'. Isolated bottot back-off at 673'. Replaced top 6'</li> <li>pressure test. Retrieved RBP and chart and looked good. Rigged de</li> <li>Post workover mechanical integrity Starting Pressure: 360 PSI</li> </ul>	er LOK-SET) st: Excessive Pressure 1-08-02 pm of casing leak at 611' 73' of 5 ½'' 14# casing v I RIH with injection pack own and released pulling grity test was witnessed bove is true and complet	2. Could no with new 5 ker and tub g unit a by Bill Pr by Bill Pr te to the bes	vitichard 11-8-02.	and belief.	DATE: December	itial essure 3, 2002

. Č