• •			
NO. OF COPIE	TO RECEIVED	•	
DISTRIE	BUTION		Form C-103
SANTAFE		MEW MEYICO OU COMPANY	Supersedes Old C-102 and C-103
FILE		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.			·
LAND OFFI	CF		5a. Indicate Type of Lease
OPERATOR			State X Fee
			5. State Oil & Gas Lease No.
	CUMPA		B-1608
(DO NO	SUNDRY THIS FORM FOR PROP	Y NOTICES AND REPORTS ON WELLS	
Ti.	USE "APPLICATIO	OSALS TO DRILL OR TO DESPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
WELL XX	GAS		7. Unit Agreement Name
2. I ame of Ope	rator WELL	OTHER-	Vacuum Aba II-i-
DI :111 D . 1 G			8. Farm or Lease Name
Phillips Petroleum Company 3. Address of Operator			Vacuum Abo Unit Btry
•			
Room 806, Phillips Bldg., Odessa, TX 79761			9. Well No. Tract 6-
14. Location of v	sei!		10. Field and Pool, or Wildcat
UNIT LETTE	, <u>L</u> 6	60 FEET FROM THE WEST LINE AND 1880 FEET FO	Transfer and a sol, of whiteen
THE SO	uth LINE SECTION	26 TOWNSHIP 17-S RANGE 35-E NM	
		NM RANGE 33-E	rm. (
		15. Elevation (Show whether DF, RT, GR, etc.)	
		3931' RKB	12. County
16.	Check An		Lea ////////
	NOTICE OF INT	oppropriate Box To Indicate Nature of Notice, Report or C	Other Data
	HOTICE OF INT		NT REPORT OF:
PERFORM REMED			
		PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY AS			
	>= <	COMMENCE DRILLING OPNS.	<u></u>
PULL OR ALTER C	>= <	CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
	>= <		<u></u>
PULL OR ALTER C	>= <	CHANGE PLANS CASING TEST AND CEMENT JOB	<u></u>
OTHER	ASING	CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
OTHER	posed or Completed Opera	CHANGE PLANS CASING TEST AND CEMENT JQB OTHER attions (Clearly state all pertinent details, and give pertinent dates, include	PLUG AND ABANDONMENT
07HER	posed or Completed Opera	OTHER OTHER OTHER	PLUG AND ABANDONMENT
17. Describe Frowork) SEE R 10-31-77: 11-01-77:	posed or Completed Opera ULE 1103. RU Ralph Johns Plugged back f	other other casing test and cement Job other state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg.	PLUG AND ABANDONMENT
07HER	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r	other attions (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. from 8414' to 8396' w/250# Hydromite. an to 8379', gun stuck, pld out of rooms.	PLUG AND ABANDONMENT
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77:	Posed or Completed Opera ULE 1703. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg,	change plans other other casing test and cement JqB other ot	ng estimated date of starting any proposed
17. Describe Frowork) SEE R 10-31-77: 11-01-77:	Posed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho	other other casing test and cement JQB other other other dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. an to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer.	ng estimated date of starting any proposed
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77:	Posed or Completed Operaule 1703. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836	change plans other ot	et. Ran overshot
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56	change Plans Casing test and cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. From 8479', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Ple to 8396'. Ram Guns perf 5-1/2" csg w/2 state 10 8396'. Ram Guns perf 5-1/2" csg w/2 state 10 8396'. Ram 2-3/8" tbg & pkr set at 8330'.	et. Ran overshot
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56	change Plans Casing test and cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. From 8479', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Ple to 8396'. Ram Guns perf 5-1/2" csg w/2 state 10 8396'. Ram Guns perf 5-1/2" csg w/2 state 10 8396'. Ram 2-3/8" tbg & pkr set at 8330'.	et. Ran overshot
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56	change plans other ot	et. Ran overshot
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77:	Posed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56 Swbd 5 hrs f/46 SD 24 hrs.	change Plans Casing test and cement Job Other attons (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. from 8414' to 8396' w/250# Hydromite. an to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. ale to 8396'. Ram Guns perf 5-1/2" csg w/2 si 66-90'. Ram 2-3/8" tbg & pkr set at 8330'. 000' to 7000', 10 BO. Swbd 6 hrs f/4500'-506', rec 2 BO, 51 BSW.	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/4 SD 24 hrs. Cleaned out Hyd	change Plans OTHER Ditions (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. File to 8396'. Ram Guns perf 5-1/2" csg w/2 si 66-90'. Ram 2-3/8" tbg & pkr set at 8330'. 1000' to 7000', 10 BO. Swbd 6 hrs f/4500'-500', rec 2 BO, 51 BSW. dromite w/bailer from 8396' to 8414'. Pld to	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77:	Posed or Completed Operative 1103. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/44 SD 24 hrs. Cleaned out Hydmaterial availage	change Plans OTHER Ditions (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. File to 8396'. Ram Guns perf 5-1/2" csg w/2 si 66-90'. Ram 2-3/8" tbg & pkr set at 8330'. 1000' to 7000', 10 BO. Swbd 6 hrs f/4500'-500', rec 2 BO, 51 BSW. dromite w/bailer from 8396' to 8414'. Pld to	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77:	RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/44 SD 24 hrs. Cleaned out Hydmaterial availar SD 24 hrs.	change Plans other control of the co	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowark) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77: 11-08-77: 11-09-77:	RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/830 Swbd 2 hrs f/50 Swbd 5 hrs f/40 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged b	change Plans Casing Test and Cement Job Other Solutions (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. File to 8396'. Ram Guns perf 5-1/2" csg w/2 state to 8396'. Ram Guns perf 5-1/2" csg w/2 state 5-90'. Ram 2-3/8" tbg & pkr set at 8330'. 1000' to 7000', 10 BO. Swbd 6 hrs f/4500'-500', rec 2 BO, 51 BSW. 1000' dromite w/bailer from 8396' to 8414'. Pld thable. 1000 back from 8414' to 8391' w/450# Under the back from 8414' to 8	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-08-77: 11-09-77: 11-10-77:	Posed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56 Swbd 5 hrs f/46 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged to Set 2-3/8" tbg	change Plans Change Plans Casing Test and Cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Can to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Cle to 8396'. Ram Guns perf 5-1/2" csg w/2 states 8330'. Coo'. Ram 2-3/8" tbg & pkr set at 8330'. Coo', rec 2 BO, 51 BSW. Committe w/bailer from 8396' to 8414'. Pld the committe w/bailer from 8391' w/450# Hydromite. Committe w/Baker "R" pkr on better et 8320'.	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowark) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77: 11-08-77: 11-09-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56 Swbd 5 hrs f/46 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged to Set 2-3/8" tbg Howco treated de	change Plans Casing Test and Cement Job Other Solutions (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. File to 8396'. Ram Guns perf 5-1/2" csg w/2 state 8330'. File to 8396'. Ram Guns perf 5-1/2" csg w/2 state 8330'. File to 8396'. Ram Guns perf 5-1/2" csg w/2 state 8330'. File to 8396'. Ram Guns perf 5-1/2" csg w/2 state 8330'. File to 8396'. Ram Sam Guns perf 5-1/2" csg w/2 state 8330'. File to 8396'. Ram Gun	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-08-77: 11-09-77: 11-10-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/49 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged t Set 2-3/8" tbg Howco treated d by 3000 gals 3%	change Plans OTHER Ditions (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. File to 8396'. Ram Guns perf 5-1/2" csg w/2 si 66-90'. Ram 2-3/8" tbg & pkr set at 8330'. O00' to 7000', 10 BO. Swbd 6 hrs f/4500'-500', rec 2 BO, 51 BSW. dromite w/bailer from 8396' to 8414'. Pld thable. back from 8414' to 8391' w/450# Hydromite. w/Baker "R" pkr on bottom at 8339'. Swbd 3 down tbg thru perfs 8366-8390' w/3000 gals 28% acid. Flushed w/24 RW. May press 4000#	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-08-77: 11-09-77: 11-10-77:	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/49 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged t Set 2-3/8" tbg Howco treated d by 3000 gals 3%	change Plans Change Plans Casing Test and Cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Can to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Cle to 8396'. Ram Guns perf 5-1/2" csg w/2 states 8330'. Coo'. Ram 2-3/8" tbg & pkr set at 8330'. Coo', rec 2 BO, 51 BSW. Committe w/bailer from 8396' to 8414'. Pld the committe w/bailer from 8391' w/450# Hydromite. Committe w/Baker "R" pkr on better et 8320'.	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW.
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77: 11-09-77: 11-10-77: 11-10-77:	Posed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56 Swbd 5 hrs f/46 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged b Set 2-3/8" tbg Howco treated d by 3000 gals 3% O#. AIR 4 BPM.	change Plans Change Plans Casine Test and Cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Can to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Cle to 8396'. Ram Guns perf 5-1/2" csg w/2 states and compared to the states of the states	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW. bg & pkr. SD until hrs, 32 BLW, swbd dry. 3% NE HCl acid followed hin zero. ISDP =
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-04-77: 11-05-77: 11-06-77: 11-07-77: 11-09-77: 11-10-77: 11-10-77:	Posed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/836 Swbd 2 hrs f/56 Swbd 5 hrs f/46 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged b Set 2-3/8" tbg Howco treated d by 3000 gals 3% O#. AIR 4 BPM.	change Plans Change Plans Casine Test and Cement Job Other Cottons (Clearly state all pertinent details, and give pertinent dates, include Son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Can to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Cle to 8396'. Ram Guns perf 5-1/2" csg w/2 states and compared to the states of the states	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW. bg & pkr. SD until hrs, 32 BLW, swbd dry. 3% NE HCl acid followed hin zero. ISDP =
17. Describe Frowork) SEE R 10-31-77: 11-01-77: 11-02-77: 11-03-77: 11-05-77: 11-06-77: 11-08-77: 11-09-77: 11-10-77: 11-11-77" Series 900	Prosed or Completed Operations. RU Ralph Johns Plugged back f RU Ram Guns, r on 2-3/8" tbg, Cleaned out ho 48 holes) f/83 Swbd 2 hrs f/56 Swbd 5 hrs f/49 SD 24 hrs. Cleaned out Hyo material availa SD 24 hrs. Howco plugged t Set 2-3/8" tbg Howco treated of by 3000 gals 3% O#. AIR 4 BPM. BOP, 3000# WP.	CHANGE PLANS OTHER DITIONS (Clearly state all pertinent details, and give pertinent dates, include son unit, pld rods & tbg. From 8414' to 8396' w/250# Hydromite. Fran to 8379', gun stuck, pld out of rope sock recovered gun. Rigged up bailer. Fle to 8396'. Ram Guns perf 5-1/2" csg w/2 state of the	et. Ran overshot hots per foot (24', Swbd 3 hrs, 16 BLW. 00', rec 2 BO, 44 BSW. bg & pkr. SD until hrs, 32 BLW, swbd dry. 3% NE HCl acid followed hin zero. ISDP =

Orig. Signed a

Engineering Advisor

DATE 11-29-77

W. J. Mueller

11-12-77: Swbd 9 hrs, FL @ 6000', rec 10 BO, 53 BL&AW.

Down 24 hrs. 11-13-77:

Pld tbg & pkr. Set 2-3/8" tbg w/anchor/catcher on bottom at 8340'. Set 11-14-77: 2" X 1-1/4" X 20' pmp at 8337'. Released Johnson unit. Pmpd 15 hrs, no gauge.

Pmpd 24 hrs, 6 BO, 60 BL&AW, 31 BSW. 11-15-77:

Pmpd 24 hrs, 12 BO, 91 BSW. 11-16-77:

Pmpd 24 hrs, 17 BO, 117 BSW. 11-17-77:

Pmpd 24 hrs, 21 BO, 121 BW. 11-18-77: Pmpd 24 hrs, 19 BO, 131 BW.

11-19-77: Pmpd 24 hrs, 20 BO, 132 BW.

Pmpd 24 hrs, 17 BO, 123 BW w/1-1/4" pmp. Abo perfs 8366-8390' restored to 11-20-77: 11-21-77: production.