MI & RU DDU & rev out CIBP @ ±8880 Make casing scrap clean w/2% KCl wi Perforate the Abo penetrating DML of 8901-8904' 3' - 8910-8921' 11' - 14' GIH w/5-1/2" RTTS Swab perfs to cle Acidize the new a of 90/10 mixture inhibitor & acid, not to exceed 500 top perforation w GIH w/2-3/8" play Set profile plug	per run to PBT tr. Spot 14 b o Reef formati charges @ 2 JS 6 shots 28 shots tota S-type packer ean up. and existing A of 28% NEFE H /xylene emulsi 00 psi. Drop w/35 bbls. FW. stic coated tb in packer. L	D of ±8930'. GI bls. 10% acetic on, top to botto PF on spiral pha 1 on 2-3/8" N-80 w bo Reef perforat Cl acid & xylene fier additives. 1 ball sealer ev Swab back load g. Set packer @ oad tbg. & annul	H w/2-3/8" N-80 acid from PBTD ( m, using a 4" OE sing as follows: workstring. Set tions (53'-106 sh containing scal Treat @ 8-10 BF ery 3.0 bbls. of & acid wtr. CO ±8800'. us from top w/pr	(8930') to 8327 ) casing gun w/d ; packer @ ±8800 nots total) w/10 le inhibitor, co PM w/max. treat f acid pumped. DOH w/tbg. & pac roduced wtr.	'. COOH. deep '. D,600 gals. orrosion ing pressure Flush to cker. (over)	
out CIBP @ ±8880 Make casing scrap clean w/2% KCl with Perforate the Abo penetrating DML of 8901-8904' 3' - 8910-8921' <u>11' - 14'</u> GIH w/5-1/2" RTTS Swab perfs to clean Acidize the new at of 90/10 mixture inhibitor & acid, not to exceed 500 top perforation to GIH w/2-3/8" play Set profile plug	per run to PBT tr. Spot 14 b o Reef formati charges @ 2 JS 6 shots 28 shots tota S-type packer ean up. and existing A of 28% NEFE H /xylene emulsi 00 psi. Drop w/35 bbls. FW. stic coated tb in packer. L	D of ±8930'. GI bls. 10% acetic on, top to botto PF on spiral pha 1 on 2-3/8" N-80 w bo Reef perforat Cl acid & xylene fier additives. 1 ball sealer ev Swab back load g. Set packer @ oad tbg. & annul	H w/2-3/8" N-80 acid from PBTD ( m, using a 4" OE sing as follows: workstring. Set tions (53'-106 sh containing scal Treat @ 8-10 BF ery 3.0 bbls. of & acid wtr. CO ±8800'. us from top w/pr	(8930') to 8327 ) casing gun w/d ; packer @ ±8800 nots total) w/10 le inhibitor, co PM w/max. treat f acid pumped. DOH w/tbg. & pac	'. COOH. deep '. D,600 gals. Drrosion ing pressure Flush to cker.	
		nstall BOP. Pul		equipment. Know	ck	
Describe Proposed or Completed ( work) SEZ RULE 1903.	Operations (Clearly sta	nte all pertinent details, an	d give pertinent dates, in	cluding estimated date o	f starting any prop	
NOTICE OF I	INTENTION TO:	COMM			RING CASING And Abandohment	
15. Elevation (Show whether DF, RT, GR, etc.) 3980 GL				12. County Lea		
West	35	17-S	35 <b>-</b> E	- NMPM.		
ocation of Well	380	North	1650	10, Flold and P Vacuum Ab	ool, or Wildcat	
Phillips Petroleum Company ddrems of Operator Room 401, 4001 Penbrook St., Odessa, Texas 79762				9. Well No.		
OIL CAS WELL AND OF OPERATOR		r Injection		Vacuum_AB	oʻjimit, Btr	
SUNDI 100 NOT USE THIS TOWN STAFFLICA	SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR HEADDON'S TO TRILL OR TO LEITEN OF PLOY SACE TO A DIFFERENT RESERVOIR. 100 NOT USE THIS FORM FOR HEADDON TO TRILL OR TO LEITEN OF PROPOSALS.)				nt Name	
				5. State Cil & G B-2519		
OPERATOR	_			Sa. Indicate Typ State XX	Fon	
FILE U.3.0.3. LAND OFFICE OPERATOR						
SANTA FE FILE U.S.G.S. LAND OFFICE	SAN				Form C-103 Revised 10-1	

1

Test tbg. to 1800 psi. Test annulus to 2000 psi. Disconnect tbg. from packer & raise tbg. 10'. Circ. annulus w/inhibited brine (1 drum Unichem 370 inhibitor/130 bbl. brine.) Connect tbg. to packer assembly & set tbg. in 2000# tension. Pressure test annulus to 500 psi. Retrieve profile plug. Move out DDU. Connect well to injection line. Put well on injection.

