

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-155-1	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator TEXACO Inc.		8. Farm or Lease Name N.M. '0' St. NCT-1
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		9. Well No. 17
4. Location of Well UNIT LETTER <u>N</u> <u>760</u> FEET FROM THE <u>South</u> LINE AND <u>2080</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Vacuum (Wolfcamp)
15. Elevation (Show whether DF, RT, GR, etc.) 4008' (DF)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Repair Waterflow</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install BOP. Set RBP in Shut-In Penn String @ 10,000'. Set RBP in Wolfcamp Zone @ 9000'. Set CIBP in collapsed 2 7/8" abandoned Penn String @ 9850' & spot 20' Cement on plug.
2. Perf. abandoned Penn String w/2-Holes through 2 7/8" & 9 5/8" csg 1640'.
3. Cement to surface 2 7/8" Csg Perfs @ 1640' w/600 Sx. Class 'H' Cement up 16" x 11 3/4" Csg. Annulus. Squeeze w/addl. 200 Sx. Class 'H' Cement. WOC. DOC & Test.
4. Pull RBP's @ 10,000' & 9000' in other zones. Return to production.

THE COMPLETION OF THIS NOTICE
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Mgr. DATE 3-10-81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

* 35' Cmt