

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANCTUARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUMMARY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR NOTICES TO WELLS OR FOR REPORTS ON WELLS TO A DIFFERENT RESERVOIR. USE THIS FORM FOR REPORTS ON WELLS TO A DIFFERENT RESERVOIR.)		5a. Indicate Type of Lease State ☒ Fee ☐			
1. Name of Operator TEXACO Inc.		5. State Oil & Gas Lease No. B-1056			
2. Address of Operator P.O. Box 728 Hobbs, New Mexico 88240		7. Unit Agreement Name			
3. Location of Well UNIT LETTER 0 460 FEET FROM THE South LINE AND 2080 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 1-3 RANGE 34-E N.M.P.M.		8. Farm or Lease Name NM 'Q' St			
13. Elevation (Show whether DF, RT, GR, etc.) 3997' (GR)		9. Well No. 5			
12. County Lea		10. Field and Pool, or without Vacuum Glorieta			
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td> NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐ </td> <td> PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐ </td> <td> SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER Addl perfs in Glorieta ☒ </td> </tr> </table>			NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER Addl perfs in Glorieta ☒
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐ OTHER ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER Addl perfs in Glorieta ☒			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up. Install BOP.
2. Clean out Blinebry to 6235' & Glorieta to 6115'. Set cement retainer @ 6115'. Set CIBP in Blinebry @ 6200'.
3. Spot 30' cement on plug. Ran 2-1/16" tubing and stung into cement retainer @ 6115'.
4. Acidize perfs 6161'-6188' w/250 gal 15% NE Acid followed w/50 sx Class 'C' cement. DOC Test to 1500#. Tested OK.
5. Perforate 2-7/8" tubing w/2-JSPF @ 6030', 64', 67', 75', 87', 90', & 6094'.
6. Set pkr @ 5997'. Acidize perforations w/2000 gal 15% NE Acid.
7. Perforate Glorieta string into Blinebry for vent string.
8. Install pumping equipment. Test and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>J. Schaffer</i></u>	TITLE <u>Asst. Dist. Supt.</u>	DATE <u>10-5-78</u>
APPROVED BY <u><i>Don L. Bogan</i></u>	TITLE <u></u>	DATE <u>OCT 10 1978</u>

CONDITIONS OF APPROVAL, IF ANY: