

TD: 6800'

Submit 3 Copies

State of New Mexico

CONDITIONS OF APPROVAL, IF ANY:

P.O. Box 2088 SINTRICT Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lease STATE FEE	o Appropriale District Office	Energy, Minerals and Natural Re-	sources Department		Keamen 1-1	-07
STATE FEE STATE FEE	20. Box 1980, Hobbs, NM 88240 P.O. Box 2088					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 7. Lease Name or Unix Agreement Name VACUUM GLORIETA WEST UNIT WILL S				6. State Oil & Gas Lease No.		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL ONTERN Name of Operator Texaco Exploration and Production Inc. 1. Address of Operator P. O. Box 730 Hobbs, NM 88240 1. Well Location Util Latter : 1650 Feet From The SOUTH Line and 660 Feet From The WEST Section 25 Township 17 S Range 34 E NMPM LEA Section 25 Township 17 S Range 34 E NMPM LEA NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON MENTER: ABANDON VACUUM BLINEBRY ZONE XO THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	DISTRICT III 000 Rio Brazos Rd., Azzec, NM 87410					
Oil Well	(DO NOT USE THIS FORM FOR PRODIFFERENT RESER (FORM C-					
Texaco Exploration and Production Inc. 1. Address of Operator P. O. Box 730 Hobbs, NM 88240 1. Well Location Unit Letter : 1650 Feet From The SOUTH Line and 660 Feet From The WEST Section 25 Township 17 S Range 34 E NMPM LEA 10. Elevation (Show whether DF, RKB, RT, GR, etc.)		OTHER				
Address of Operator P. O. Box 730 Hobbs, NM 88240 Line and 660 Feet From The WEST Section 25 Township 17 S Range 34 E NMFM LEA Section 25 Township 17 S Range 34 E NMFM LEA 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4019° DF Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REFORM REMEDIAL WORK PLUG AND ABANDON CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB CHER: ABANDON VACUUM BLINEBRY ZONE CASING TEST AND CEMENT JOB COMMENCE OF RULL 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	. Name of Operator					
P. O. Box 730 Hobbs, NM 88240 L Well Location Ualt Letter L : 1650 Feet From The SOUTH Line and 660 Feet From The WEST Section 25 Township 17 S Range 34 E NMPM LEA 10. Elevation (Show whether DP, RKB, KT, GR, etc.) A019' DF 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: ABANDON VACUUM BLINEBRY ZONE X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	· · · · · · · · · · · · · · · · · · ·					
Well Lossion Usit Letter	•	VACUUM GLORIETA				
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4019' DF	L Well Location Unit Letter L : 16	50 Feet From The SOUTH		- -	WEST	Line County
NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: ABANDON VACUUM BLINEBRY ZONE TO THER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	Section 25	10. Elevation (Show whether I				
NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN FULL OR ALTER CASING OTHER: OTHE						
ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB OTHER: ABANDON VACUUM BLINEBRY ZONE 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).						
EMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN CASING TEST AND CEMENT JOB OTHER: ABANDON VACUUM BLINEBRY ZONE 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	NOTICE OF INT	ENTION TO:	SUE	SEQUENT RE	PURI UF:	
CASING TEST AND CEMENT JOB OTHER: ABANDON VACUUM BLINEBRY ZONE 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	□ AL	TERING CASING	
OTHER: ABANDON VACUUM BLINEBRY ZONE 12 Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed worth) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	EMPORARILY ABANDON	GOPNS. 🗌 PL	UG AND ABANDO	NMENT 🗌		
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	PULL OR ALTER CASING CASING TEST A			CEMENT JOB		
1) Notify NMOCD 24 hours prior to plugging operations. 2) MIRU Pulling Unit. Pull rods, pump and tubing. 3) Rig up Black Warrior (first-call supplier). 4) Run 4.343" gauge ring to 6560'. 5) RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	OTHER: ABANDON VACUUM BLIN	EBRY ZONE X	OTHER:		- 	
 MIRU Pulling Unit. Pull rods, pump and tubing. Rig up Black Warrior (first-call supplier). Run 4.343" gauge ring to 6560'. RIH with 5.5" Cast Iron Bridge Plug on wireline and set at 6550'. Dump 35' of cement on top of CIBP (two dump bailer runs). 	work) SEE RULE 1103.					
6550'. 6) Dump 35' of cement on top of CIBP (two dump bailer runs).	2) MIRU Pul 3) Rig up B 4) Run 4.34	ling Unit. Pull rod lack Warrior (first 3" gauge ring to 65	s, pump and -call suppli 60'.	tubing. er).		<u>-</u>
	6550'. 6) Dump 35'	of cement on top o	f CIBP (two	dump bailer	runs).	•
						alkon
I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE PRODUCTION ENGINEER DATE SEPT 10, 19	1 -00			GINEER	DATE SEPT 10	0, 1992
SIONATURE AND						
TYPEOR PRINT NAME DANIEL A. DON'TAIN					THE INTERIOR	
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR DATE SEP 15'		CT I SUPERVISOR			SEP	15'92

RECEIVED
SEP 1 4 1992
OCD HOBBS OFFICE

RECEIVED

SEP 1

OCD HOBBS OFFICE