

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-20319

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
B-155-1

7. Lease Name or Unit Agreement Name
New Mexico "O" ST NCT-1

8. Well No.
22

9. Pool name or Wildcat
Vacuum Glorieta/Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

Texaco E&P Inc.

3. Address of Operator

P.O. Box 730; Hobbs, NM 88240

4. Well Location

Unit Letter M : 500 Feet From The South Line and 560 Feet From The West Line

Section 36

Township 17 S

Range 34E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/22:MIRU P/U L/D Rods Notify OCD 1/21/96.

1/23:RU WL Truck RIH on z side Tag @ 6028 w/ gauge ring RIH on y side to 6400 Set CICR in z side @ 5820 y side 6000.

1/24:Finish RIH w/ 2 1/16" TBG sting into CICR in y side 6000' Get a rate on a vacuum. Load back side test to 1000 PSI Mix & Pump 55sx CL C Cmt well on a vacuum WOC test 4 PM. RIH w/ 40 stands Load back side test to 1000 PSI Get on TBG Pump BBLs well on vacuum Mix & Pump 55 more sx CL C Cmt Well on vacuum. Pulled 40 stand Shut dwn. Test on 1/25 Well went on a vacuum on y side Mix & Pump 55 sx cmt Pumped below CICR 6000 POOH RIH on z side Mix & Pump 45 sx below CIC at 5820 sqz off 1500 PSI Cap CICR @ 5820 in z side 10 sx Cmt POOH Shut dwn.

1/26:RIH on y side sting into CICR @ 6000 Could Pump into Perf 3200-1 bbl/min sting out Mix 45 sx Cmt Got 35 sx Below Pres up to 3500 PSI Stop Pumping Held 2000 Sting Out Put 10 sx on top POOH on y side.

1/26:RIH on z side Spot 10 sx 4550 - 4144 POOH to 3733 Spot 10 sx 3733 - 3327 POOH.

1/30:RIH on y side Tag Cmt 5253 POOH 4550-Spot 10 sx 4550-4144 POOH to 3733 Spot 10 sx cnt 3733-3327 POOH 2800 Spot 10 sx Cmt 2800-2794 POOH

1/31:RIH w/ Perf Gun Perf @ 2800 on z side POOH RIH w/ 2 7/8 CICR Set @ 2750 RIH w/ 2 1/16 TBG & Stinger SQZ CL C Cmt Below CICR @ 2750 O Press POOH Shut Dwn

2/01:RIH w/ stinger sting into RET on z side Test 1000 PSI Held Good Sting Out Pump 10 sx Plug on top of CICR @ 2750-2344 POOH Take stinger off back, in hole to 1600 Spot 10 sx CL C Plug 1600-1194 POOH z side RIH on y side 1600 mix 10 sx CL C Plug in y side 1600-1194 POOH cut 2 7/8 CSG on y side @ 1000' Load csg cut csg on z side Mix & Pump 100 sx CL C Plug @ 1000' POOH Shut Dwn for the day. Continued on Back of Form.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE

P&A Supervisor

DATE

2/2/96

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for state use)

APPROVED BY

[Signature]

TITLE

OIL & GAS

DATE


MAY 14 1996

CONDITIONS OF APPROVAL, IF ANY:

2/2:R/H Tag Cmt in 11 3/4 830' POOH to 400' Circulate 11 3/4 Pipe to Surf w/ 230 sx CL C Cmt RD move off well Plugged Out 2/2/96. Cut Well head off Weld on Dry Hole Marker.

P&A: 2-02-96

TEXACO E&P INC.
NM "O" STATE NCT-1 No. 22
API# 30 025 20319



500 FSL & 560 FWL
SEC 36, T1N 17 S, RANGE 34 E
ELEVATION: 4010 DF
COMPLETION DATE: 12-03-63
COMPLETION INTERVALS: 5929 - 6035 (Glorieta)
6726 - 6774 (Blinebry)