

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20505
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-155-1
7. Lease Name or Unit Agreement Name	New Mexico "O" State NCT-1
8. Well No.	15
9. Pool name or Wildcat	Vacuum Glorieta

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco ESP, Inc.
3. Address of Operator P. O. box 3109 - Midland, TX 79701	4. Well Location Unit Letter I : 1800 Feet From The South Line and 560 Feet From The East Line

Section 36	Township 17S	Range 34-E	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3997 RKB					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
1. Notify NMCO prior to plugging and abandonment of well.
 2. This is a dual complete well w/2' strings of 2-7/8" casing for production.
 3. Rig up on Y-side, set CIRC @ 5800' & sqz 90 sks cmt below retainer into perms. Unsting & cap retainer w/10 sks cmt f/5800'-5500'. Circ. csg w/25# per bbl. salt gel mud.
 4. Spot 45 sks cmt plug f/4550'-3250' (San Andres 4500', Queen - 3700'-8-5/8" csg shoe @ 3300').
 5. (Y-side) Perf. & sqz 2840' w/60 sx cmt, cmt retainer @ 2800' (Yates 2790'), cap circ. w/10 sxs cmt f/2800'-2500'.
 6. (Y-side) Perf. @ 1600' & sqz. w/60 sxs cmt w/CIRC @ 1550'. (6-27-80 sqz. csg leaks down ann. of 11-3/4" & 8-5/8" w/650 sxs cmt. Circ. cmt by 2-7/8" csg to surf.) May not be able to pump into. Spot 10 sxs cmt f/1550'-1250' to cap CIRC.
 7. (Y-side) Spot 20 sxs cmt f/600'-surface.
 8. TIH w/2-1/16" tub. on X-side tag CIBP @ 6565'; circ. csg w/25# per bbl. salt gel mud. Spot 35 sx cmt plug f/6565'-5500'.
 9. (X-side) Spot 45 sx cmt plug f/4550'-3250' (San Andres-4500', Queens 3700'-8-5/8" csg shoe @ 3300').
 10. (X-side) Spot 15 sx cmt plug f/2840'-2500' (Yates 2790').
 11. (X-side) Spot 20 sx cement plug f/600' - surface.
 12. Nipple down BOP, cut off wellhead, cap well, install dry hole marker. Clean location, rig down & move off.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. J. Harding III TITLE Operations Engineer DATE 6/8/95
TYPE OR PRINT NAME R. J. Harding III TELEPHONE NO. 915/683-4816

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN 13 1995

Present
New Mexico "O" STATE NCT-1

15

11 3/4" 42# CSg

SET @ 1550' cmt w/ 1000SXS.

cmt. cmt CIRC.

drlg 15" hole

(6-27-80 - cmt down 11 3/4" @ 8 5/8"

CSg, ANN. w/ 650 SX CSg | CAL 1495-208'
cmt CIRC up 8 5/8" by 2 7/8" ANN. to 5920'.

(tight spots f/ 2472-2800')

8 5/8" CSg SET @ 3300'

24# @ 32# J-55-H40

cmt w/ 900SXS.

cmt. CIRC. drlg 11" hole

7 7/8" hole f/ 3300-6915 T.D.

RAN 2 7/8" CSg ON X side to 6909'

RAN 2 7/8" CSg ON Y side to 6915'

cmt both strings together w/ 1200SXS

cmt. CAL TOC. 3084' (CIRP 6565)

X side - Perf 6681-6808

Y-side 5865-5871

Y-side perf @ 5932'-6159'

Y-side perf - 6180'-6185'

TD 6915'

