STATE OF NEW MEXICO ÉNERGY AND MINERALS DEPARTMENT

WO. OF COPIES SECCIVES	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONDITIONS OF APPROVAL, IF ANY

jj

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-78

FILE	5a. Indicate Type of Lease
U.8.0.8.	State X Fee
LAND OFFICE OPERATOR	5. State Oil & Gus Lease No.
	B-7428-2
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT —" (FORM C-1GI) FOR SUCH PROPOSALS.)	
1.	7, Unit Agreement Name
OIL GAB OTHER Replug P&A well.	
2. Name of Operator	8. Farm or Lease Name
*Amoco Production Company	State "CV"
1. Address of Operator	9, Well No.
Room 401, 4001 Penbrook, Odessa, Texas 79762	4
4. Location of Well	10. Field and Pool, or Wildcat
T. 2210 Court 220	Vacuum Abo Reef
UNIT LETTER	
17_C 35_F	
THE West LINE, SECTION 25 TOWNSHIP 17-S RANGE 35-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3923' RKB	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	ب
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB	r X n
*Phillips Petroleum Comp	any as operator of East
Vacuum Gb/SA Unit did re	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	
17. Describe Atobosis of Combiners Obstations forces.	estimated date of starting any proposed
work) SEE RULE 1 (03	
work) SEE RULE 1 (03	No. R-5897.
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900',	No. R-5897.
work) SEE RULE 1 (03	No. R-5897.
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide.	No. R-5897. pulled 900' of 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle	No. R-5897. pulled 900' of 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80	No. R-5897. pulled 900' of 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle	No. R-5897. pulled 900' of 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'.
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'.
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2"
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off.
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csg-ran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csg-ran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs.	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at
06-25-80MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csg-ran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80-Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80-Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg.
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg. R)
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80-Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80-TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80-Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80-Pulled 4-1/2" csg-ran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80-Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80-Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80-Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg. R)
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg. R)
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg. R)
06-25-80-MI Jamison & Caffey WS Unit, backed off 4-1/2" csg at 900', & 26-80 csg to rerun w/guide. 06-27-80Ran 4-1/2" csg w/guide. Ran 3-7/8" bit on 2-3/8" tbg. Cle & 29-80 07-01-80TOC 3890'. Set BP at 8650', dumped 3 sxs cmt on plug. 07-02-80Pulled 4-1/2" csg. Spotted 21 sxs cmt at 6240', 81 sxs at csg at 3824'. 07-03-80Pulled 4-1/2" csgran tbg open end to 3876', spotted 50 sx & 06-80 07-07-80Tagged plug at 3686', spotted 50 sxs cmt at 3422', ran bond 2770' to surface, pipe free to 300'. Spotted 10 sxs cmt at 2850'. 07-08-80Pressed 8-5/8" csg to 1000#, perfd 8-5/8" csg at 1905' w/4 & 09-80 1798', cmtd w/130 sxs. 07-10-80Tstd perfs at 1905' w/1000#, OK. Spotted 10 sxs cmt at 178	No. R-5897. pulled 900' of 4-1/2" aned out to 4500'. 5000'. Shot 4-1/2" s cmt. Crew off. log in 8-5/8" csg from 3356' and 30 sxs at holes. Set ret at 5'. Pulled tbg. R)

07-11-80--Perfd 8-5/8" csg at 350', circ to surface 325 sxs Cl "C" cmt. Tagged cmt in & 12-80 8-5/8" csg at 12' from surface. MO Jamison & Caffey Unit. Installed dry hole marker. Well P&A.

1.3.

JUU 186 T