		•	Form C-103
NO. OF COPIES RECEIVED	<del> </del>	<u>.</u>	Supersedes Old
DISTRIBUTION	NEW MEXICO OF	L CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
SANTA FE	NEW MEXICO UI	E CONSERVATION COMMISSION	F110C(144 1-1-02
FILE	<del> </del> i		5a. Indicate Type of Lease
U.S.G.S.	1		State Fee E
LAND OFFICE	<del>  </del>		5. State Oil 6 Gas Lease No.
OPERATOR	<u></u>	•	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  (DO NOT USE THIS FORM FOR PERMIT -" (POR C-101) FOR SUCH PROPOSALS.)			
	LICATION FOR PERMIT -** (FORM C-101	) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1. OIL X GAS WELL WELL	OTHER-		8. Farm of Lease Name
2. Name of Operator			
Mobil Oil Corporation 3. Address of Operator			State "DD" ("A)
3 Greenway Plaza East, Suite 800, Houston, Texas 77046			1
			10. Field and Pool, or Wildcat
4. Location of Well  535  UNIT LETTER D 467 FEET FROM THE West LINE AND 500 FEET FROM			Vacuum Abo North
UNIT LETTER , FEET FROM THE WEST LINE AND FEET FROM			THINITING TO SEE THE S
North	SECTION TOWNSHIP	17-S 35-E	
THELINE,	SECTION TOWNSHIP .	RANGE	MMPM. (
mmmmm	15 Flourities (Shor	v whether DF, RT, GR, etc.)	12. County
	13. Elevation (5.16)	whether bi , Ki , OK, etc.)	Lea
ÖH HILLIH HILLI			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABAI	NDON REMEDIAL WORK	ALTERING CASING
		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	<del>[</del>	1
PULL OR ALTER CASING			T
OTHEROTHER			
OTHERL			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.	, and operations ( ) and ( )		
		000	•
1. Pump well off and pressure up tbg to 300 psi			
2. Pump 500 gals C-dex scale dissolver down tbg-csg annulus. Do not use C-dex 2 or			
C-dex Plus scale converters			
3. SI 24 hrs			
4. Pump back C-dex; Pull rods and pump			
5. Spot 500 gals 7½% N.E. iron stabilized HCl across perforated interval.			
6. Pull tbg.			
7. G.I.H. w/ 4" csg gun. Perforate Abo (1-JSPF) as follows: 9287' - 9320' (34 shots)			
8. G.I.H. w/ treating the and pkr. Set pkr. @ 9250' +			
9. Acidize Abo (9287' - 9320') w/ 6,000 gals N.E. iron stabilized HCl using up to 60			
RCNBS to obtain selectivity. Inject acid at 4-6 BPM, not exceeding 4500 psi			
differential pressure on tbg. Acid should contain 1% retarder and 3 gal/1000			
friction reducing agent.			
10. Displace and overdisplace w/ 2500 gal treated 2% KCl water.			
11. S.I 2 to 4 hrs.			
12. Pull treating equipment			
13. Swab to clean up			
14. Run prod. equip. and return to production.			
	emotion shove is true and complete t	o the best of my knowledge and belief.	
is. I hereby certify that the into	smarron acces on and and acceptable to	,	
111	1 0	Authorized Asset	6 Jan Jao
SIGNED O. W. A	+ LIDore	Authorized Agent	DATE 6/20/78
n	orig. Signed by		FETRE O D TO THE
	erry Sexton	TITLE	DATE JUN 23 1978