

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| | |
|--|--|
| WELL API NO. | 30-025-20946 |
| 5. Indicate Type of Lease | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. | B-155 |
| 7. Lease Name or Unit Agreement Name | |
| New Mexico "O" State NCT-1 | |
| 8. Well No. | 24 |
| 9. Pool name or Wildcat | Vacuum Glorieta, Wolfcamp, Abo North |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | |
| 3994' DF | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. Type of Well: | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator | Texaco Exploration and Production Inc. |
| 3. Address of Operator | P.O. Box 730 Hobbs, New Mexico 88240 |
| 4. Well Location | Unit Letter P : 860 Feet From The South Line and 660 Feet From The East Line Section 36 Township 17-S Range 34-E NMPM Lea County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | |
| 3994' DF | |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| PLUG AND ABANDON <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU pulling unit. Install BOP.
- 2) TIH Z casing string (Glorieta) with DP and shoe and clean out to 10,100' (CIBP w/ 30' cmt at 5150'). Load hole up to Glorieta perfs with salt gel mud. TOH.
- 3) TIH X casing string (Abo) with 1 5/8" DP and shoe and clean out to 9100'. TOH.
- 4) Fish string of stuck 1" Kobe tubing in Y casing string (Wolfcamp). Clean out to 10,040'.
- 5) Freepoint casing.
- 6) By wireline set CIBP in Y string at 9990'. Cap w/ 35' cmt.

(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. L. Dumas TITLE Engineer's Assistant DATE 3-5-92
TYPE OR PRINT NAME. TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 09 '92

- 7) By wireline set CIBP in X string at 9080'. Cap w/ 35' cmt.
- 8) By wireline set CIBP in Z string at 5850'. Cap w/ 35' cmt.
- 9) Load all three casing strings with salt gel mud.
- 10) By wireline set CIBP's in Y string at 5850' and 4418'. Cap plugs with 35' cmt.
- 11) By wireline set CIBP's in X string at 5850' and 4418'. Cap plugs with 35' cmt.
- 12) By wireline set CIBP in Z string at 4418'. Cap w/ 35' cmt.
- 13) Cut all three strings of 2 7/8" casing at freepoint (Approx. 2800'). TOH with two of the strings. Use the third for workstring.
- 14) Spot 55 sx cmt across csg stubs and base of salt from 2635'-2800'. Tag plug.
- 15) Load hole with salt gel mud.
- 16) Pull up and spot 45 sx cmt across surface casing shoe and top of salt from 1450'-1585'. Tag plug.
- 17) Pull up and spot 33 sx cmt below fresh water from 365'-465'. Tag plug.
- 18) Pull up and spot 10 sx cmt from surface-30'.
- 19) Cut off wellhead. Install marker. Clean location.

RECEIVED

MAR 09 1992

OCD HOBBS OFFICE