Submit 3 Copies State of New Mexico	1 1	
to Appropriate Energy Amerals and Natural Resources Department District Office	k -89	
OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 3002520957	
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. 011026	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name	
(FORM C-101) FOR SUCH PROPOSALS.) Type of Well: OR. GAS CT.	New Mexico "CG" State NCTZ#2	
WELL X WILL OTHER Name of Operator	8. Well No.	
Texaco E&P Inc.	11	
Address of Operator	9. Pool name or Wildcat	
P.O. Box 3109 Midland, TX 79702	Vacuum Glorietta	
Unit Letter F : 2310 Feet From The North Line and 175	Feet From The West Line	
Section 29 Township 17S Range 35E	NMPM Lea County	
10. Elevation (Show whether DF, RKB, KT, GR, etc.)		
*/////////////////////////////////////	Control of National States and Color Date	
Check Appropriate Box to Indicate Nature of Notice, I	report or other Dam.	
11. Check Appropriate Box to Indicate Nature of Notice, I	BSEQUENT REPORT OF:	
11. Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUI		
Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	BSEQUENT REPORT OF: ALTERING CASING	
Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	BSEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT	
Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: SUI PERFORM REMEDIAL WORK PLUG AND ABANDON EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING PULL OR ALTER CASING CASING TEST AND COMMENCE	BSEQUENT REPORT OF: ALTERING CASING OPNS. PLUG AND ABANDONMENT	
Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON EMPORABLY ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND COMMENCE OF THE PROPRIES CASING TEST AND COMMENCE CASING TEST AND COMMENCE OF THE PROPRIES CASING TEST AND COMMENCE CASING TEST A	BSEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB	
Check Appropriate Box to Indicate Nature of Notice, I NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLIN CASING TEST AND COMMENCE	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce.	
Check Appropriate Box to Indicate Nature of Notice, Interpolar Complete South Plug and Abandon (Commence Drilling Casing Test and Commence Drilling Casing Test and Ca	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB CHARLES STATING ANY PROPOSED Tinding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres)	
Check Appropriate Box to Indicate Nature of Notice, In NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE OF COMMENCE DRILLING CASING TEST AND COMMENCE OF COMMENCE DRILLING CASING TEST AND COMMENCE OF COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING CASI	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface.	
NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING PROPERTION TO THER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomork) SEE RULE 1103. 1. Notify NMOCD prior to moving on well. 2. Est. injection rate down tub. (2-7/8" tub is produc. 3. SQ 150 sxs class C cmt. (into Glorietta perf. 6157—WOC & tag. 4. Circ. csg. w/25# per/bbl. salt gel & brine to surface. 5. POOH to 4500'. Spot 5 sxs class C cmt. plug f/4500—6. POOH to 3000' & spot 15 sxs class C cmt. plug f/350 of lower salt) 7. POOH to 1750 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt. plug f/350 -sice poon to 350 spot 15 sxs class C cmt.	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface.	
NOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING OTHER: 1. Notify NMOCD prior to moving on well. 2. Est. injection rate down tub. (2-7/8" tub is produc. 3. SQ 150 sxs class C cmt. (into Glorietta perf. 6157-WOC & tag. 4. Circ. csg. w/25# per/bbl. salt gel & brine to surface. 5. POOH to 4500'. Spot 5 sxs class C cmt. plug f/4500-6. POOH to 3000' & spot 15 sxs class C cmt. plug f/350-18. POOH to 350 spot 15 sxs class C cmt. plug f/350 -si 8. POOH to 350 spot 15 sxs class C cmt. plug f/350 -si 8. POOH to 350 spot 15 sxs class C cmt. plug f/350 -si 1. Notify NMOCD prior to moving on well. 2. Est. injection rate down tub. (2-7/8" tub is produc. 3. SQ 150 sxs class C cmt. (into Glorietta perf. 6157-WOC & tag. 4. Circ. csg. w/25# per/bbl. salt gel & brine to surface. 5. POOH to 4500'. Spot 5 sxs class C cmt. plug f/350-10. 6. POOH to 3000' & spot 15 sxs class C cmt. plug f/350 -si 8. POOH to 350 spot 15 sxs class C cmt. plug f/350 -si	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface.	
Check Appropriate Box to Indicate Nature of Notice, INOTICE OF INTENTION TO: ERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING CASING TEST AND COMME	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface.	
NOTICE OF INTENTION TO: SUIT SERFORM REMEDIAL WORK PLUG AND ABANDON CASING TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE TEST AND COMMENCE TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING TEST AND COMMENCE DRILLING CASING TEST AND COMMENCE DRILLING	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface. arker.	
Check Appropriate Box to Indicate Nature of Notice, INOTICE OF INTENTION TO: SUIT NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND CONTHER: DITHER: DITHER: DITHER: DITHER: DITHER: 1. Notify NMOCD prior to moving on well. 2. Est. injection rate down tub. (2-7/8" tub is produc. 3. SQ 150 sxs class C cmt. (into Glorietta perf. 6157-WOC & tag. 4. Circ. csg. w/25# per/bbl. salt gel & brine to surface. 5. POOH to 4500'. Spot & sxs class C cmt. plug f/4500-6. POOH to 3000' & spot le sxs class C cmt. plug f/3000 of lower salt) 7. POOH to 1750 spot le sxs class C cmt. plug f/350 -sice of the pool of well head & weld on cap & install dry hole moved the pool of the pool of the pool of the pool of well head & weld on cap & install dry hole moved the pool of	ALTERING CASING ALTERING CASING NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed tion csg.) 6177) displace cmt. to 6000. ce. 4400 (WOC & tag) (S. Andres) 0-2750 (WOC & tag) (Yates & base 600. WOC & tag. (top of salt) urface. arker. S Engineer DATE 10-5-94	