

Page 2
Mescalero Ridge Unit 35 #10
Plug and Abandonment Procedure

8. TIH with sawtoothed collar on tubing to 1,840'.
9. With 5 ½" x 8 5/8" casing valve open, break circulation down tubing and up annulus with plug mud.
10. Once circulation is established, mix and pump 25 sxs "C" cement and circulate to EOT in a balanced plug. Slowly POOH standing back tubing. Let cement set overnight.
11. TIH with sawtoothed collar on tubing to tag cement at ±1,840'. POOH laying down tubing to 185' then stand back remainder.
12. MIRU Electric line. TIH and perforate the casing with 4 holes at 285'. POOH and RDMO Electric line unit.
13. TIH with sawtoothed collar on tubing to 185'.
14. With 5 ½" x 8 5/8" casing valve open attempt to break circulation down tubing and up annulus with plug mud.
15. Once circulation is established, mix and pump 25 sxs "C" cement and circulate to EOT in a balanced plug. Slowly POOH standing back tubing. Let cement set overnight.
16. TIH with sawtoothed collar on tubing to tag cement at ±185'. POOH laying down tubing to 60'.
17. Mix and pump 10 sxs "C" cement and circulate to surface. Slowly POOH laying down tubing.
18. Cut off wellhead and affix dry hole marker as per OCD guidelines.
19. Clean and level location. Reseed as per OCD reclamation guidelines.

RECEIVED
OCT 29 99
BLM
ROSWEIL, NM