

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-1020-1	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-		7. Unit Agreement Name
2. Name of Operator		Central Vacuum Unit
3. Address of Operator		8. Farm or Lease Name
P. O. Box 720, Hobbs, New Mexico 88240		Central Vacuum Unit
4. Location of well		9. Well No.
UNIT LETTER <u>H</u> , <u>2710</u> FEET FROM THE <u>North</u> LINE AND <u> </u> FEET FROM		10. Field and Pool, or Wildcat
THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17-S</u> RANGE <u>24-E</u> NMPM.		Vacuum Grayburn
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
2491' (GR)		Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Repair Waterflow, Addl. perfs., & Treat</u> ☒	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & pump. Install RBP. Pull tubing.
2. Set RBP @ 4000' & dump 20' sand on plug.
3. Perforate 4 1/2" csg w/2-20 @ 1625'. Set cement retainer @ 1550'.
4. Cement 7 5/8" x 4 1/2" csg Annulus w/225 sx. class II cement. Circulate cement. Squeeze w/2000. 200 sx. 100. Run temperature survey.
5. 100. 100. Test. Pull RBP.
6. Perforate 4 1/2" csg w/2-18PF @ 4470', 85', 4511', 4000', 54', 65', 68', 4705', 10', 17', 20', 27', & 4730'.
7. Set RTTS Tool @ 4580'. Acidize w/2000 gals. 20% NEFE HCl Acid & 18 Ball sealers. Flush w/25 bbls. 2% Kcl water.
8. Set RBP @ 4575' & RTTS @ 4410'. Acidize w/3000 gals. 20% NEFE HCl Acid & 18 ball sealers. Flush w/25 bbls. 2% Kcl water. Pull RBP & RTTS.
9. Run production equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 1/12/81

APPROVED BY [Signature] TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 12 1981