	UNITED STATES PARTME. OF THE INTER		N.M. OILOC S. DIVISION					
BUR	EAU OF LAND MANAGEM	ENT P.C. Sola 1980 Hobbs, NM 88241	FORM APPROVED Budget Bureau No, 1004-0135 Expires March 31, 1993					
SUNDR Do not use this form for propos Use "APPLI	 Lease Designation and Serial No. NM-NM05519A If Indian, Allottee or Tribe Name N/A If Unit or CA, Agreement Designation 							
Well	* <u>WIW</u>		Mescalero Ridge 26 891007465					
2. Name of Operator DEVON ENERGY CORPOR	Mescalero Ridge 26 Unit #7							
3. Address and Telephone No. 20 NORTH BROADWAY, S	9. API Well No. 30-025-22333							
 Location of Well (Footage, Sec., T., R. 990' FSL & 990' FWL Unit M 	10. Field and Pool, or Exploratory Area Pearl (Queen-Penrose) 11. County or Parish, State							
Lea County, New Mexico								
	ATE BOX(s) TO INDICATE NA	TURE OF NOTICE, REPO	ORT, OR OTHER DATA					
TYPE OF SUBMISSION	PE OF SUBMISSION TYPE OF ACTION							
Notice of Intent	Abandonr Recomple		Change of Plans					
Subsequent Report			Non-Routine Fracturing Water Shut-Off					
Final Abandonment Notice	Altering (0	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In December, 1997, attempts to repair the casing in the Mescalero Ridge 26 Unit #7 failed and the well was SI for evaluation. During July, 1998, Devon Energy Corporation (Nevada) plans to permanently abandon the

this well as per the following attached procedures.

- 1. Procedure of work planned
- 2. Current well bore schematic
- 3. Proposed P&A well bore schematic

APPROVED PETER W. CHESTER	7
JUL 7 1998	
BUREAU OF LAND NANAGEMENT ROSWELL RESOURCE AREA	
the second se	

14. I hereby certify that the foregoing is true and correct						
O I O N. I		Candace R. Graham				
Signed Candace R. Araham	Title	Engineering Technician	Date			
(This space for Federal or State office use)						
Approved by Conditions of approval, if any:	Title _		Date			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representatio to any matter within its jurisdiction.

DEVON ENERGY CORPORATION

Interoffice Correspondence

Monday, June 22, 1998

- TO: Rick Clark
- FROM: W.M. Frank
- RE: SWD Well P&A Procedure MRU 26-7 990' FSL & 990' FWL Section 26-T19S-R34E Lea County, New Mexico
 - Well Data: Elevation 3740' GL

TD 5031' PBTD 5029'

Casing: 8-5/8" 28# @ 223' Cement Circulated 5-1/2" 15.5# @ 5031' Cmt w/350 sx

Procedure

- 1. Blow down well until water flow slows to manageable rates.
- 2. MIRU DDPU. ND injection head. NU BOPE.
- 3. TIH, to 4614' RKB, w/915' of tubing already hanging using workstring as make-up tubing. Circulate hole w/9.0 or better plugging mud.
- 4. With EOT @ the top perf, mix and pump a 30 sx "C" balanced plug to the EOT. Slowly POOH standing back 10 stands.
- 5. Reverse circulate tubing clean. WOC f/4 hours. TIH w/tubing and tag plug. If plug in place POOH to 3600'. If plug is not in place, spot cement as necessary to bring TOC plug to ±4500'.
- 6. With EOT @ ±3600', mix and pump a 30 sx "C" balanced plug to the EOT. Slowly POOH standing back 10 stands.
- 7. Reverse circulate tubing clean. WOC f/4 hours. TIH w/tubing and tag plug. If plug in place POOH to 1900'. If plug is not in place spot cement as necessary to bring TOC plug to ±3400'.
- 8. With EOT @ ±1900', mix and pump a 30 sx "C" balanced plug to the EOT. Slowly POOH standing back 10 stands.

MRU 26-7 SWD Well P&A Page 2

- 9. Reverse circulate tubing clean. WOC f/4 hours. TIH w/tubing and tag plug. If plug in place POOH to 760'. If plug is not in place spot cement as necessary to bring TOC plug to ±1700'.
- 10. With EOT @ ±760', mix and pump a 30 sx "C" balanced plug to the EOT. Slowly POOH standing back 10 stands.
- Reverse circulate tubing clean. WOC f/4 hours. TIH w/tubing and tag plug. If plug in place POOH laying down all tubing. If plug is not in place spot cement as necessary to bring TOC plug to ±560'.
- 12. MIRU electric line unit. TIH and perforate 5 ¹/₂", 15.5# casing at 273'. With casing valve open, try and break circulation. If able to pump into perfs RDMO electric line unit.
- 13. With the casing valve open, mix and pump 70 sxs "C" cement. Circulate cement to surface.
- 14. Cut off wellhead below ground level and weld P&A stub to casing. Make sure P&A stub contains well information as per BLM regulations.

DEVON ENERGY CORPORATION (NEVADA) WELLBORE SCHEMATIC



DEVON ENERGY CORPORATION (NEVADA) WELLBORE SCHEMATIC

