

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22984
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-0220
7. Lease Name or Unit Agreement Name Bush State
8. Well No. 1
9. Pool name or Wildcat Scharb Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Manzano Oil Corporation 505/623-1996	
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	
4. Well Location Unit Leader <u>I</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>12</u> Township <u>19 South</u> Range <u>34 East</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3945' GL	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Place CIBP @ 9400' + 35' cement on top.
2. Place 20 sks plug across sq. hole @ 7000'.
3. 100' cement plug from 5000 to 5100'.
4. 100' cement plug at 8-5/8" shoe (3999'). 50' below and 50' above.
5. Find free point on 5-1/2" csg. Approx 1500'. Cut off. Cut 8-5/8" at same place. Recover pipe.
6. Place 100' cement plug across csg stubs. 50' below and 50' above. Tag.
7. Place 100' cement plug across 13-3/8" shoe @ 406'. 50' below and 50' above.
8. Install 10 sks surface plug and dry hole marker

REVISION MUST BE NOTICED 24 HOURS PRIOR TO THE BEGINNING OF FOLLOWING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Hernandez TITLE Engineering Tech. DATE 8/4/95
TYPE OR PRINT NAME Allison Hernandez TELEPHONE NO. _____

(This space for State Use) ORIGINAL FILED IN DISTRICT SECTION

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: NOTICED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

AUG 22 1995