N.M. OILCONS. COMMISSION P.O. BOX 1980

		HOBBS NEW MEXICO 8824	-
Form 3160-5 (June 1990)	DEPARTMEN	ED STATES T OF THE INTERIOR AND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5 Lease Designation and Serial No.
	orm for proposals to dri	AND REPORTS ON WELLS II or to deepen or reentry to a di ⁴ ferent R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
	SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1 Type of Well Oil Well Sas Well	Other		8. Well Name and No.
	0X 671 - age, Sec., T., R., M., or Survey De D'FSL \$ 76	o'FWL	9. API Well No. 9. API Well No. 30-025-23475 10. Field and Pool, or Exploratory Area La Rica Morrow Gos 11. Country or Parish, State Lea County, N.M.
Unit Lette	APPROPRIATE BOXIS	<u>T-19-S, R-34-E</u>)) TO INDICATE NATURE OF NOTIC	
	SUBMISSION		OF ACTION
(D) Subseq	of Intent uent Report Abandonment Notice	Abandonment Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
give subsurface ite		al depths for all markers and zones pertinent to this work (redure. RECUre. NECEIVE
Signed Chur (This space for Federa (ORIG Approved b)	e pregoing is try and correct Lotte Deleton J or State office use) . SG.2.) JOE G. LAN	915) 685-7607 	Production 10: 0 AREA 52 Production 10: 0 AREA 52 AREA 52 ARE
		knowingly and willfully to make to any department or ager	ncy of the United States any false, fictitious or fraudulent statements

*See Instruction on Reverse Side



Drig Engr. Ra
Drig Supt:
Resv Engr. CHm
Prod Engr.
Prod Supt:

South Permian Asset Group

FIELD:	La Rica	LEASE:	Pipeline Federal	May 13, 1997 NO: 1	
Location: Sec:	660' FSL & 760' FWL 4	Twn: County:	19S Lea	Rge: 34E	
		county.		State: NM	

REASON FOR WORK: Abandon the Lower Morrow formation & recomplete in the Upper & Middle Morrow Formations.

CONDITION OF HOLE:

Formation Date From Lower Morrow 8/6/70 13420	To	SPF	# Holes	
Formation Date From	* -			
PERFORATIONS:				
5 1/2" 17 & 20# N-80 & P-110 @ 14585' w/	1350 sx (T	OC @11000)' ts)	
9 5/8" 40# K-55 & N-80 @ 5451' w/ 600 sx				
13 3/8" 48# K-55 @420' w/460sx(circ)				
CASING RECORD:				

Lower Morrow	5/23/96	13420	13442	4	84	
TUBING DETAIL:		425 1	2 3/8" 4.7# L-8	30 AB mod.		13335

		10000
1	2 3/8" SN	1
1	2 3/8" 4.7# L-80 AB mod.	NA
1	Baker seal bore assembly	NA
	Total Tbg	
	Btm Tbg.	13352

REGULATORY REQUIREMENTS:

Obtain BLM approval.





PIPELINE FEDERAL #1

PROCEDURE:

- 1. Obtain BLM approval via notice of intent sundry notice.
- 2. RU kill truck and pump 50 bbls approved plugging fluid down 2 3/8" tubing.
- 3. MIRU well service unit. Perform audit.
- 4. ND wellhead. NU BOP. TOOH w/tubing & seal assembly.
- 5. RU wireline, run junk basket & gauge ring to top of permanent packer @ 13370'. Set CIBP on top of packer @ 13368'. Dump 35' cement on bridge plug. (BLM requirements).
- 6. TIH w/5 1/2 casing scraper & 4 3/4" bit to 13320'.
- RU acid pump truck & pump 500 gal 15% HCI pickle acid to bottom of tubing. Reverse circulate hole w/310 bbl 2% KCI. Test casing to 2000#. Spot 5 bbls acetic acid across perforation zone 13100'-13320'.
- 8. TOOH w/bit & scraper.
- RU wireline to perforate upper & middle morrow formations as follows: Run pack-off & full lubricator. 4" casing gun w/premium charges, 120° phasing, 2 spf as follows: 13090'-13102', 13119'-13122', 13178'-13182', 13218'-13220', 13252'-13258', 13290'-13294'. 68 total holes. (reference Schlumberger GR/N dated 8/3/70.)
- TIH w/2 3/8", 4.7#, L-80, eue 8rd, AB mod. w/tubing set packer. (possible packer- Halliburton perma-latch w/on-off tool w/1.875 "X" profile & 1.791"
 "XN" profile on bottom.) Hydro-test tubing in hole to 8000 psi.
- 11. Circulate annulus w/packer fluid & set packer in 20k compression @13000'.
- 12. ND BOP, test tree to 5000 psi, Flange up tree.
- 13. Swab & evaluate, (fluid to tank).
- 14. RU BJ to acidize via 2 3/8" tree saver (10k) w/4000 gal 20Q CO₂ acid system, (2400 gals 7 1/2% HCI + 800 gals methanol + 800 gals CO₂) plus additives carrying 100 ballsealers. Flush w/2130 gals 20Q CO₂ treated water(1700 gals 2% KCI + 430 gals CO₂). (see acid recommendation.)

- 15. Record ISDP, 5,10,15 min SITP, RD acid company & tree saver.
- 16. Flow back well slowly on 10/64" choke, record pressures and recover fluids in tank.

- 17. Evaluate, swab if needed.
- 18. Establish stabilized production, evaluate possible fracture treatment.
- 19. Perform static BHP tests & AOF 4 pt. test.