

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-23923
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Santa Fe A <i>Com</i>
8. Well No. 1
9. Pool name or Wildcat <i>N. Vac. abo</i>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>619</u> Feet From The <u>west</u> Line Section <u>7</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4012' GR 4023' DF</u>	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Perforate additional interval ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed procedure to add Abo perforations and acidize: Mi and RU DDU. Cooh with rods and pump. Insure well is dead. Install BOP. COOH with 2-3/8" tubing. Run SLM and check PBTD. GIH with drill bailer and clean out to 8841'. Perforate with 4" casing gun at 2 JSPF on spiral phasing

Interval	Ft.	Shots
8633' - 8648'	15'	30
8778' - 8785'	7'	14
8813' - 8819'	6'	12
8827' - 8839'	12'	24
	40'	80

GIH with 5-1/2" packer-type RBP and 5-1/2" RTTS-type packer on 2-7/8" workstring. Set RBP on bottom and packer at 8600'. Swab to clean perforations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. L. Maples TITLE Reg. & Proration Assist DATE 02-13-90
TYPE OR PRINT NAME J. L. Maples TELEPHONE NO. (915) 367-1411

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 19 1990

Set packer at 8760' and swab dry prior to acidizing. Pressure test all surface lines to 5500 psi. Pump 1800 gallons of 15% NEFe HCl with one ball sealer every 35 gallons at a maximum rate of 3 BPM and a maximum pressure of 5000 psig. Flush with 51 bbls of 2% KCl water. Swab test interval to determine productivity. Move RBP to 8760' and packer to 8670'. Swab dry prior to acidizing. Acidize with 600 gallons of 15% NEFe HCl. Attempt to load annulus and monitor during treatment. Drop one ball sealer every 30 gallons. Flush with 50 bbls of 2% KCl water. Maximum rate is 3 BPM and the maximum pressure is 5,000 psi. Move RBP to 8670' and set packer at 8600'. Swab dry prior to acidizing. Acidize perforations with 1500 gallons of 15% NEFe HCl. Pressure annulus to 500 psi and monitor during treatment. Drop one ball sealer every 40 gallons. Flush with 50 bbls 2% KCl water. Set RBP on bottom and packer at 8600'. Swab back spent acid water. COOH with RBP tubing and packer. Return well to production.

regpro/apinc/sfel

RECEIVED

DEC 10 1993