

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24088
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-155-1
7. Lease Name or Unit Agreement Name New Mexico "O" State NCT-2	
8. Well No.	21
9. Pool name or Wildcat	Vacuum Abo North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4047' GR	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration and Production Inc.
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	4. Well Location Unit Letter L : 2030 Feet From The South Line and 760 Feet From The West Line Section 33 Township 17-S Range 34-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4047' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) RUPU. Install BOP.
- 2) TIH with 5 1/5" CIBP on workstring. Set at 8700'. Cap with 50' cmt.
- 3) Pull up and circulate hole with salt gel mud consisting of 10 lb brine with 25 lbs of gel per barrel.
- 4) Pull up and spot a 25 sx cmt plug from 6340'-6100'. Tag plug.
- 5) Pull up and spot a 25 sx cmt plug from 4140'-3900'. Tag plug.
- 6) Pull up and spot a 25 sx cmt plug from 1730'-1490'. Tag plug. TOH.
- 7) Perf two sqz holes at 400'. (CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.C. Duncan TITLE Engineer's Assistant DATE 6-9-92  
TYPE OR PRINT NAME M.C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

THIS FORM IS THE PROPERTY OF  
THE STATE OF NEW MEXICO  
IT IS TO BE APPROVED.

- 8) Rig up cmt equipment to wellhead. Establish circulation to surface through sqz holes at 400'. Sqz with 150 s or until cmt is circulated to surface.
- 9) Cut off wellhead. Install marker. Clean locati

800000

1000000

1000000

1000000