

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24946
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. K-4513 and K-6237
7. Lease Name or Unit Agreement Name Midway State COM
8. Well No. 5
9. Pool name or Wildcat Lovington Devonian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator GREENHILL PETROLEUM CORPORATION	
3. Address of Operator 11490 WESTHEIMER, SUITE 200/HOUSTON, TEXAS 77077-6841	
4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>12</u> Township <u>17S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU PU. Move pumping unit. Install BOP. POOH w/production equipment. (07-21-94)
2. RU wireline. Set CIBP at 11,500'. Spot 5 sx cmt. from 11,500'. Circulate mud.
3. Perforate at 8,800'. Set cmt. retainer at 8,700'. Squeeze perms w/50 sx cmt. - spot 15 sx cmt. on top of retainer.
4. Cut csg at 4,600' - try to pull, could not. TIH w/tbg to 4,650' and spot 25 sx cmt. - SDON.
5. Tag cmt. at 4,395'. Free pt and cut csg at 550'. Pull and lay down.
6. Perforate 8 5/8" csg at 500'. Circulate mud. TIH w/tbg to 600' - circulate cmt. down 8 5/8" to 600' and up 11 3/4" csg to surface.
7. Cut off wellhead. Weld on dry hole marker, fill cellar, clean location. (07-26-94)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lori A. Hodge TITLE Landman DATE 08-3-94
TYPE OR PRINT NAME Lori A. Hodge TELEPHONE NO. (713) 589-8484

GARY W WINK

FIELD REPRESENTATIVE II

ORIGINAL SIGNED BY
GARY WINK
FIELD REP II

JAN 03 1995

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY _____